

[«Back to Inspection Results](#)**ZIEGLER** **CAT****SPECIFICATIONS****2004 CATERPILLAR 262B****Customer Owned Certified****SKID STEER LOADERS**

<b>Inspection Number:</b> 577811	<b>Serial #:</b>	PDT00843
<b>Date Created:</b> 10/02/2008 08:06:49 AM CDT	<b>Engine Serial #:</b>	CJS04554
<b>Last Updated:</b> 10/02/2008 08:26:49 AM CDT	<b>Transmission Serial #:</b>	N/A
<b>Originated By:</b> Todd Miller	<b>SMU/Hrs:</b>	10182
<b>Inspector:</b> Todd Miller	<b>Last Scheduled Oil Sample:</b>	N/A
<b>Reviewer:</b> N/A	<b>Last Cat Track System Inspection:</b>	N/A
<b>Salesman:</b> Kim Greenfield	<b>Last Preventative Maintenance:</b>	N/A
<b>Location:</b> RATHBUN, Iowa, United States	<b>Recommendation:</b>	no recommendation
<b>Asking Price:</b> N/A	<b>Final Price:</b>	N/A

**Client**

**Name:** Dwayne McAninch  
**Company:** McAninch

**City:** Des Moines  
**State:** Iowa  
**Country:** United States

**Features**

- EROPS
- AIR CONDITIONER
- HEATER
- BUCKET
- COUPLER, HYDRAULIC
- AUXILIARY HYDRAULICS
- HYDRAULICS, STANDARD FLOW

**Condition****GENERAL APPEARANCE**

	<b>Condition - Remarks</b>	<b>Parts</b>	<b>Labor</b>
<b>Radiator Grill &amp; Shroud</b>	Good		
<b>Eng. Enclose Hood / Stack</b>	Good		
<b>Fenders</b>	Good		
<b>Fuel Tank</b>	Good		
<b>Crankcase Guard / Battery Box</b>	Good		
<b>Main Frame Welds</b>	Good		
<b>Counterweight</b>	Good		
<b>Pre-Cleaner Bowl</b>	Good		
<b>Cab or Canopy</b>	Good		
<b>Steps / Ladder</b>	Good		
<b>Grab Irons</b>	Good		
<b>Paint</b>	Fair		
<b>Sheet Metal</b>	Good		

	Condition - Remarks	Parts	Labor
S.O.S. Taken	No		
Cleaning Required	Yes		

**SAFETY ITEMS**

	Condition - Remarks	Parts	Labor
Safety Decals In Place	Yes		
Safety Decals Legible	Yes		
ROPS	Yes		

	Condition - Remarks	Parts	Labor
Horn	Good		
Parking Brake	Good		

**GAUGES, OPERATOR STATION, CONSOLE**

	Condition - Remarks	Parts	Labor
Dash Console	Good		
Meter	Good		
Gauges	Good		
Switches	Good		
Windshield Wipers	Good		
Heater	Good		
Interior Lights	Good		
Seat Cushion / Arm Rest	Good		
Floor Boards	Good		
EMS Panel / Warnings	Good		
Door Latches	Good		
Glass/Mirrors	Fair - frt. glass cracked		
Hydraulic Controls	Good		
Air Conditioner	Good		
Seat Belt	Good		

	Condition - Remarks	Parts	Labor
Back Up Alarm	Yes		

**ENGINE**

	Condition - Remarks	Parts	Labor
Oil Leaks	No		
Blow By	No		
Knocking	No		
Compression in Radiator	No		
Water in Oil	No		
Fluid Levels OK?	No		

	Condition - Remarks	Parts	Labor
Anti-Freeze Color	normal		

Oil Pressure (H/L/N)	normal		
Smoke (B/D/L/W)	normal		

	Condition - Remarks	Parts	Labor
Operating Condition	Good		
Turbocharger / Blower	Good		
Fuel Injection System	Good		
Governor	Good		
Engine Supports	Good		
Air Cleaners	Good		
Exhaust / Muffler	Good		
Belts / Pulleys	Good		

**COOLING SYSTEM**

	Condition - Remarks	Parts	Labor
Radiator	Good		
Coolers	Good		
Hoses	Good		
Water Pump	Good		
Fan	Good		
Fan Drive	Good		

	Condition - Remarks	Parts	Labor
Leaks	No		

**ELECTRICAL, STARTING AND CHARGING SYSTEM**

	Condition - Remarks	Parts	Labor
Batteries / Cables	Good		
Starter	Good		
Alternator	Good		
Wiring	Good		
Pre-Heater	Good		
Lighting	Good		

	Condition - Remarks	Parts	Labor
Block Heater	Yes		
Ether Aid	Yes		

**TANDEM/GEARS/BEARINGS/CHAINS**

	Condition - Remarks	Parts	Labor
Front Axle	Good		
Rear Axle	Good		
Travel Motors	Good		
Travel Pumps	Good		
Travel Controls	Good		
Lines / Linkages	Good		
Operating			

Condition	Good		
-----------	------	--	--

**HYDRAULICS**

	Condition - Remarks	Parts	Labor
Operating Condition	Good		
Tank	Good		
Pumps & Valves	Good		
Hose Lines	Fair - minor leaks		
Detent Switch	Good		
Tilt Cylinder	Good		
Lift Cylinders	Good		

	Condition - Remarks	Parts	Labor
Leaks	Yes		

**BUCKET**

	Condition - Remarks	Parts	Labor
Cutting Edges	Good		
Bucket Bottom	Good		
Bucket Sides	Good		
Bucket Linkage	Good		
Loader Pins & Bushings	Good		
Loader Frame	Good		
Quick Coupler	Good		

	Condition - Remarks	Parts	Labor
Bucket S/N	sgp16394		

**TIRES**

	Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Right Front	caterpillar			No	Yes	No
Left Front	caterpillar			No	Yes	No
Right Rear	caterpillar			No	Yes	No
Left Rear	caterpillar			No	Yes	No
Tire Size	12-16.5NHS					

	Condition - Remarks	Parts	Labor
Spare	No		
Floation Chains / Tracks	No		

**COMMENTS, MISC. REPAIRS, GENERAL REMARKS**

	Parts	Labor
machine operates good, needs tires, cleaned, and hyd. leaks fixed		

**Photos**

---

Click thumbnails to enlarge.



Caterpillar Confidential: Green. Copyright © 2008, Caterpillar Inc. All Rights Reserved.