

# Butler Machinery Company

## Skid Steer / Multi Terrain Loaders

Date: <u>10/10/2008</u>	Make: <u>BobCat</u>
Inspector Name: <u>Josh Fields</u>	Model: <u>S205</u>
Customers Name: <u>BMC Used Equipment</u>	Machine S/N: <u>528412433</u>
Salesman: <u>Austin Calavera</u>	Year: <u>2005</u>
Machine Location: <u>Sioux Falls</u>	Pictures Taken Yes <input type="checkbox"/> No <input type="checkbox"/>
Total Machine Hours: <u>1856</u>	S.O.S Taken Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
Hour Meter Reading: <u>1856</u>	Notes: _____

### Skid Steer/ Multi Terrain Loaders Configuration

- |  |  |  |
|--|--|--|
| <input checked="" type="checkbox"/> EROPS          | <input type="checkbox"/> OROPS                           | <input checked="" type="checkbox"/> Air Conditioner      |
| <input checked="" type="checkbox"/> Heater         | <input checked="" type="checkbox"/> Bucket               | <input checked="" type="checkbox"/> Hydraulic Coupler    |
| <input type="checkbox"/> Forks                     | <input checked="" type="checkbox"/> Auxiliary Hydraulics | <input checked="" type="checkbox"/> High Flow Hydraulics |
| <input type="checkbox"/> Hydraulics, Standard Flow | <input checked="" type="checkbox"/> 2 Speed Travel       | <input type="checkbox"/> Anti-Theft System               |
| <input type="checkbox"/> Product Link              | <input checked="" type="checkbox"/> Self Leveling        | <input type="checkbox"/> CE Plate                        |

### General Appearance

Condition: N=New VG=Very Good G=Good F=Fair P=Poor NA=Not Applicable							
	N	VG	G	F	P	NA	Comments
Radiator Grill & Shroud			X				
Eng. Enclose Hood / Stack			X				
Fender			X				
Fuel Tank			X				
Crankcase Guard or Bottom Guard			X				
Main Frame Welds			X				
Bumper						X	
Counterweight						X	
Pre-Cleaner Bowl						X	
Cab or Canopy		X					
Steps & Ladders			X				
Grab Irons			X				
Paint			X				
Sheet Metal			X				
Overall Appearance			X				

Comments:	
	Estimated Cost Of Repairs:

### Safety Items

Condition: N=New VG=Very Good G=Good F=Fair P=Poor NA=Not Applicable							Comments
N	VG	G	F	P	NA		
		X					
			X				It doesn't work right away.
		X					
		X					
Safety Decals in Place & Legible	Yes <input checked="" type="checkbox"/>		No <input type="checkbox"/>				One decal in the front is missing.
Comments:							
							Estimated Cost Of Repairs:

### Gauges, Operator Station, Console

Condition: N=New VG=Very Good G=Good F=Fair P=Poor NA=Not Applicable							Comments
N	VG	G	F	P	NA		
	X						
		X					
		X					
		X					
				X			Wipers are broke off.
		X					
				X			Did not cool.
		X					
		X					
		X					
		X					
		X					
		X					
		X					
Current Parts Manual	Yes <input type="checkbox"/>		No <input checked="" type="checkbox"/>				

Current Safety Manual	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	
Current O&MM	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	
ROPS Certification Plate	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	
Comments:			
			Estimated Cost Of Repairs:

### Engine

Condition: N=New VG=Very Good G=Good F=Fair P=Poor NA=Not Applicable							
	N	VG	G	F	P	NA	Comments
Operating Condition			<input checked="" type="checkbox"/>				
Turbocharger / Blower			<input checked="" type="checkbox"/>				
Fuel Injection System			<input checked="" type="checkbox"/>				
Engine Supports			<input checked="" type="checkbox"/>				
Air Cleaners			<input checked="" type="checkbox"/>				
Exhaust & Muffler			<input checked="" type="checkbox"/>				
Oil Leaks	Yes <input checked="" type="checkbox"/>			No <input type="checkbox"/>			Leak on back side of valve cover.
Blow By	Yes <input type="checkbox"/>			No <input checked="" type="checkbox"/>			
Knocking	Yes <input type="checkbox"/>			No <input checked="" type="checkbox"/>			
Compression in Radiator	Yes <input type="checkbox"/>			No <input checked="" type="checkbox"/>			
Water in Oil	Yes <input type="checkbox"/>			No <input checked="" type="checkbox"/>			
Fluid Levels Ok	Yes <input type="checkbox"/>			No <input checked="" type="checkbox"/>			Coolant low, hydraulic oil low
EPA Decal	Yes <input checked="" type="checkbox"/>			No <input type="checkbox"/>			
Anti-Freeze Color	Brown						
Oil Pressure	Ok						
Exhaust Smoke	Good						
Engine Make & Model	Kubota V2403						
Comments:							
							Estimated Cost Of Repairs:

### Cooling System

Condition: N=New VG=Very Good G=Good F=Fair P=Poor NA=Not Applicable							
	N	VG	G	F	P	NA	Comments
Radiator			<input checked="" type="checkbox"/>				
Coolers			<input checked="" type="checkbox"/>				
Hoses			<input checked="" type="checkbox"/>				
Water Pump			<input checked="" type="checkbox"/>				
Fan			<input checked="" type="checkbox"/>				
Fan Drive/ Pulleys			<input checked="" type="checkbox"/>				

	N	VG	G	F	P	NA	Comments
Belts			X				
Worn Pulleys	Yes			No	X		
Leaks	Yes			No	X		
Comments:							
							Estimated Cost Of Repairs:

### Electrical, Starting and Charging System

Condition: N=New VG=Very Good G=Good F=Fair P=Poor NA=Not Applicable							
	N	VG	G	F	P	NA	Comments
Batteries / Cables			X				
Starter			X				
Alternator			X				
Wiring			X				
Pre-Heater / Glow Plugs			X				
Lighting					X		One head light is out.
Block Heater	Yes	X		No			
Ether Aid	Yes			No	X		
Comments:							
							Estimated Cost Of Repairs:

### Tandems/Gears/Bearings/Chains

Condition: N=New VG=Very Good G=Good F=Fair P=Poor NA=Not Applicable							
	N	VG	G	F	P	NA	Comments
Front Axle			X				
Rear Axle			X				
Travel Motors			X				
Travel Pumps			X				
Travel Controls			X				
Lines & Linkages			X				
Operating Condition			X				
Oil Leaks	Yes			No	X		
Comments:							
							Estimated Cost Of Repairs:

### Hydraulics

Condition: N=New VG=Very Good G=Good F=Fair P=Poor NA=Not Applicable							
	N	VG	G	F	P	NA	Comments
Operating Condition			X				
	N	VG	G	F	P	NA	Comments

Tank			X				
Pump & Valves			X				
Hose & Lines			X				
Tilt Cylinder			X				
Lift Cylinder			X				
Oil Leaks	Yes			No	X		
Comments:							
							Estimated Cost Of Repairs:

### Attachments / Work Tools

Condition: N=New VG=Very Good G=Good F=Fair P=Poor NA=Not Applicable							
	N	VG	G	F	P	NA	Comments
Auger						X	
Trencher						X	
Cold Planer						X	
Wheel Saw						X	
Broom						X	
Landscape Tiller						X	
Stump Grinder						X	
Grapple Bucket						X	
Hammer						X	
Snow Blower						X	
Other						X	
Comments:							
							Estimated Cost Of Repairs:

### Bucket

Condition: N=New VG=Very Good G=Good F=Fair P=Poor NA=Not Applicable							
	N	VG	G	F	P	NA	Comments
Cutting Edges					X		Cutting edge is wore out.
Teeth / Adapters						X	
Bucket Sides					X		Edges are worn, crack on right side.
Bucket Floor				X			

							N		VG	G	F	P	NA	Comments		
Bucket Linkage					X											
Loader Pins & Bushings					X											
Loader Frame					X											
Quick Coupler (Manual or Hyd)					X									Hyd.		
Edges Turned		Yes				No	X									
B.O.C.E.		Yes	X			No										
W.O.C.E.		Yes				No	X									
Bucket Width		73"														
Bucket Make		Bobcat														
Comments:																
														Estimated Cost Of Repairs:		

### Tires

		Bias		Radial										
	Mfg.	Type	Ply	Star Rating/ Load Rating	Depth in 1/32	% Remaining	Cut, Abrasions							
Right Front	Firestone	DWA DT Force	10		3/4	New	None							
Right Rear	Firestone	DWA DT Force	10		3/4	New	None							
Left Front	Firestone	DWA DT Force	10		3/4	New	None							
Left Rear	Firestone	DWA DT Force	10		3/4	New	None							
Recapped	Yes	No	X											
Tire Size														
Comments:														
												Estimated Cost Of Repairs:		

### Undercarriage


Condition: N=New VG=Very Good G=Good F=Fair P=Poor NA=Not Applicable																
							N		VG	G	F	P	NA	Comments		
Tracks / Belts Condition														X		
Idlers														X		
Rollers														X		
Sprockets														X		
Roller Frame														X		
Track / Belt Width																
% Worn																
Comments:																
														Estimated Cost Of Repairs:		










1

2

3









1

