

[«Back to Inspection Results](#)**MUSTANG** **SPECIFICATIONS****2006 CATERPILLAR 242B****Customer Owned Certified****SKID STEER LOADERS**

<b>Inspection Number:</b>	648998	<b>Serial #:</b>	BXM02762
<b>Date Created:</b>	05/29/2009 02:59:22 PM CDT	<b>Engine Serial #:</b>	N/A
<b>Last Updated:</b>	05/29/2009 03:10:24 PM CDT	<b>Transmission Serial #:</b>	N/A
<b>Originated By:</b>	DOUGLAS HARRISON	<b>SMU/Hrs:</b>	1037
<b>Inspector:</b>	DOUGLAS HARRISON	<b>Last Scheduled Oil Sample:</b>	N/A
<b>Reviewer:</b>	N/A	<b>Last Cat Track System Inspection:</b>	N/A
<b>Salesman:</b>	N/A	<b>Last Preventative Maintenance:</b>	10/15/2008
<b>Location:</b>	HOUSTON, Texas, United States	<b>Recommendation:</b>	no recommendation
<b>Asking Price:</b>	N/A	<b>Final Price:</b>	N/A

**Client**

**Name:** n/a n/a  
**Company:** Warren Cat

**State:** Unknown  
**Country:** [Not Specified]

**Description**

Auction Machine

**Features**

- OROPS
- BUCKET
- HYDRAULICS, STANDARD FLOW

**Condition****GENERAL APPEARANCE**

	Condition - Remarks	Parts	Labor
<b>Radiator Grill &amp; Shroud</b>	Good		
<b>Eng. Enclose Hood / Stack</b>	Good		
<b>Fenders</b>	Good		
<b>Fuel Tank</b>	Good		
<b>Crankcase Guard / Battery Box</b>	Good		
<b>Main Frame Welds</b>	Good		
<b>Bumper</b>	Good		
<b>Cab or Canopy</b>	Good		
<b>Steps / Ladder</b>	Good - bucket step pad bent		
<b>Grab Irons</b>	Good		
<b>Paint</b>	Fair - stencils coming off and scratched up		
<b>Sheet Metal</b>	Good		

	Condition - Remarks	Parts	Labor
S.O.S. Taken	No		
Cleaning Required	No		

**SAFETY ITEMS**

	Condition - Remarks	Parts	Labor
Safety Decals In Place	Yes		
Safety Decals Legible	Yes		
ROPS	Yes		

	Condition - Remarks	Parts	Labor
Horn	Very Good		
Parking Brake	Very Good		

**GAUGES, OPERATOR STATION, CONSOLE**

	Condition - Remarks	Parts	Labor
Dash Console	Very Good		
Meter	Very Good		
Gauges	Very Good		
Switches	Very Good		
Interior Lights	Very Good		
Seat Cushion / Arm Rest	Good		
Floor Boards	Very Good		
EMS Panel / Warnings	Very Good		
Glass/Mirrors	Very Good		
Hydraulic Controls	Very Good		
Seat Belt	Very Good		

	Condition - Remarks	Parts	Labor
ROPS Certification Plate	Yes		
Back Up Alarm	Yes		

	Condition - Remarks	Parts	Labor
Fuel Level	1/8 th		

**ENGINE**

	Condition - Remarks	Parts	Labor
Oil Leaks	Yes - front seal area wet		
Blow By	No		
Knocking	No		
Compression in Radiator	No		
Water in Oil	No		
Fluid Levels OK?	Yes		

	Condition - Remarks	Parts	Labor
Anti-Freeze Color	red		

Oil Pressure (H/L/N)	normal		
Smoke (B/D/L/W)	black		

	Condition - Remarks	Parts	Labor
Operating Condition	Good		
Turbocharger / Blower	Good		
Fuel Injection System	Good		
Governor	Good - foot throttle not getting idle all the time		
Engine Supports	Good		
Air Cleaners	Good		
Exhaust / Muffler	Good		
Belts / Pulleys	Good		

**————— COOLING SYSTEM —————**

	Condition - Remarks	Parts	Labor
Radiator	Good		
Coolers	Good		
Hoses	Good		
Water Pump	Good		
Fan	Good		
Fan Drive	Good		

	Condition - Remarks	Parts	Labor
Leaks	No		

**————— ELECTRICAL, STARTING AND CHARGING SYSTEM —————**

	Condition - Remarks	Parts	Labor
Batteries / Cables	Good		
Starter	Good		
Alternator	Good		
Wiring	Good		
Pre-Heater	Good		
Lighting	Good		

**————— TANDEM/GEARS/BEARINGS/CHAINS —————**

	Condition - Remarks	Parts	Labor
Front Axle	Good		
Rear Axle	Good		
Travel Motors	Good		
Travel Pumps	Good		
Travel Controls	Good		
Lines / Linkages	Good		
Operating Condition	Good		

**————— HYDRAULICS —————**

--	--	--	--

	Condition - Remarks	Parts	Labor
Operating Condition	Good		
Tank	Good		
Pumps & Valves	Good		
Hose Lines	Good		
Tilt Cylinder	Good		
Lift Cylinders	Good		

	Condition - Remarks	Parts	Labor
Leaks	No		

**———— BUCKET ————**

	Condition - Remarks	Parts	Labor
Cutting Edges	Good		
Teeth / Adapters	Good		
Bucket Bottom	Good		
Bucket Sides	Good		
Bucket Linkage	Good		
Loader Pins & Bushings	Good		
Loader Frame	Good		
Quick Coupler	Good		

**———— TIRES ————**

	Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Right Front	galaxy	34		No	No	No
Left Front		36		No	No	No
Right Rear		38		No	No	No
Left Rear		36		No	No	No
Tire Size	12 - 16.5 nhs right rear wheel missing one lug nut					

## Photos

Click thumbnails to enlarge.





Caterpillar Confidential: Green. Copyright © 2009, Caterpillar Inc. All Rights Reserved.