

**Louisiana
Machinery**

SPECIFICATIONS
2003 CATERPILLAR 277
Customer Owned Certified
MULTI TERRAIN LOADERS

Inspection Number:	647966	Serial #:	CNC02352
Date Created:	05/21/2009 11:44:49 AM CDT	Engine Serial #:	N/A
Last Updated:	05/21/2009 11:53:04 AM CDT	Transmission Serial #:	N/A
Originated By:	Samy Cashio	SMU/Hrs:	1720
Inspector:	N/A	Last Scheduled Oil Sample:	N/A
Reviewer:	N/A	Last Cat Track System Inspection:	N/A
Salesman:	N/A	Last Preventative Maintenance:	N/A
Location:	HOUSTON, Texas, United States	Recommendation:	no recommendation
Asking Price:	N/A	Final Price:	N/A

Client
Name: Louisiana Machinery

City: RESERVE

State: Louisiana

Country: United States

Description

1.) Machine was last serviced on 11/7/08 at 1719 Hours. (250 HR. PM.) 2.) Bucket Cutting Edges need to be turned 3.) Machine has new Rubber Tracks. 4.) Bucket linkage P&B has moderate wear. (Normal wear indicative of hours.)

Features

- OROPS
- BUCKET
- SELF LEVELING

Condition
GENERAL APPEARANCE

	Condition - Remarks	Parts	Labor
Radiator Grill & Shroud	Good		
Eng. Enclose Hood / Stack	Good		
Fuel Tank	Good		
Crankcase Guard / Battery Box	Good		
Main Frame Welds	Very Good		
Cab or Canopy	Good - Canopy		
Steps / Ladder	Good - One Step is bent (but is ok)		
Grab Irons	Good		
Paint	Very Good		
Sheet Metal	Good		

	Condition - Remarks	Parts	Labor

S.O.S. Taken	No		
Cleaning Required	No		

SAFETY ITEMS

	Condition - Remarks	Parts	Labor
Safety Decals In Place	Yes		
Safety Decals Legible	Yes		
ROPS	Yes - ROPS		

	Condition - Remarks	Parts	Labor
Horn	Good		
Parking Brake	Good		

GAUGES, OPERATOR STATION, CONSOLE

	Condition - Remarks	Parts	Labor
Dash Console	Good		
Meter	Good		
Gauges	Good		
Switches	Good		
Seat Cushion / Arm Rest	Good		
Floor Boards	Good		
EMS Panel / Warnings	Good		
Door Latches	Good		
Glass/Mirrors	Good		
Hydraulic Controls	Good		

	Condition - Remarks	Parts	Labor
ROPS Certification Plate	Yes		
Back Up Alarm	Yes		

ENGINE

	Condition - Remarks	Parts	Labor
Oil Leaks	No		
Blow By	No		
Knocking	No		
Compression in Radiator	No - Normal Circulation		
Water in Oil	No		
Fluid Levels OK?	Yes		

	Condition - Remarks	Parts	Labor
Anti-Freeze Color	Red		
Oil Pressure (H/L/N)	Normal		
Smoke (B/D/L/W)	Black		

	Condition - Remarks	Parts	Labor
Operating Condition	Good		

Turbocharger / Blower	Good		
Fuel Injection System	Good		
Governor	Good		
Engine Supports	Good		
Air Cleaners	Good		
Exhaust / Muffler	Good		
Belts / Pulleys	Good		
Oil Filter Condition (CUT)	Good		

————— COOLING SYSTEM —————

	Condition - Remarks	Parts	Labor
Radiator	Good		
Coolers	Good		
Hoses	Good		
Water Pump	Good		
Fan	Good		
Fan Drive	Good		

	Condition - Remarks	Parts	Labor
Leaks	No		

————— ELECTRICAL, STARTING AND CHARGING SYSTEM —————

	Condition - Remarks	Parts	Labor
Batteries / Cables	Very Good		
Starter	Very Good		
Alternator	Very Good		
Wiring	Very Good		
Lighting	Very Good - All lights are working		

————— TANDEM/GEARS/BEARINGS/CHAINS —————

	Condition - Remarks	Parts	Labor
Front Axle	Good		
Rear Axle	Good		
Travel Motors	Good		
Travel Pumps	Good		
Travel Controls	Good		
Lines / Linkages	Good		
Operating Condition	Good		

————— HYDRAULICS —————

	Condition - Remarks	Parts	Labor
Operating Condition	Good		
Tank	Good		
Pump & Valves	Good		
Hoses / Lines	Good		
Tilt Cylinder	Good		
Lift Cylinders	Good		

Filter Condition (CUT)	Good - DID NOT CUT		
-------------------------------	--------------------	--	--

	Condition - Remarks	Parts	Labor
Leaks	No		

————— BUCKET —————

	Condition - Remarks	Parts	Labor
Cutting Edges	Fair - Bucket Edges could use a turn		
Bucket Bottom	Good		
Bucket Sides	Good		
Bucket Linkage	Good		
Loader Pins & Bushings	Good		
Loader Frame	Good		
Quick Coupler	Good - Manual		

	Condition - Remarks	Parts	Labor
Bucket Capacity	66"		

————— UNDERCARRIAGE —————

	Condition - Remarks	Parts	Labor
Roller	Good		
Track / Belt Condition	New - New Track Belts		
Roller Frame	Very Good		
Idlers	Very Good		
Sprocket	Very Good		