

[«Back to Inspection Results](#)**MUSTANG** **SPECIFICATIONS****2007 CATERPILLAR 256C****Customer Owned Certified****SKID STEER LOADERS**

Inspection Number:	649003	Serial #:	DWS00153
Date Created:	05/29/2009 03:12:30 PM CDT	Engine Serial #:	N/A
Last Updated:	05/29/2009 03:24:04 PM CDT	Transmission Serial #:	N/A
Originated By:	DOUGLAS HARRISON	SMU/Hrs:	18332
Inspector:	DOUGLAS HARRISON	Last Scheduled Oil Sample:	N/A
Reviewer:	N/A	Last Cat Track System Inspection:	N/A
Salesman:	N/A	Last Preventative Maintenance:	N/A
Location:	HOUSTON, Texas, United States	Recommendation:	no recommendation
Asking Price:	N/A	Final Price:	N/A

Client

Name: n/a n/a
Company: Warren Cat

State: Unknown
Country: [Not Specified]

Description

Auction Machine

Features

- OROPS
- BUCKET

Condition**GENERAL APPEARANCE**

	Condition - Remarks	Parts	Labor
Radiator Grill & Shroud	Very Good		
Eng. Enclose Hood / Stack	Very Good		
Fenders	Very Good		
Fuel Tank	Very Good		
Crankcase Guard / Battery Box	Very Good		
Main Frame Welds	Very Good		
Bumper	Very Good		
Cab or Canopy	Good		
Steps / Ladder	Very Good		
Grab Irons	Very Good		
Paint	Good - stencil burned on back door where new filter bracket welded on		
Sheet Metal	Good		

	Condition - Remarks	Parts	Labor
S.O.S. Taken	No		
Cleaning Required	Yes - engine compartment		

SAFETY ITEMS

	Condition - Remarks	Parts	Labor
Safety Decals In Place	Yes		
Safety Decals Legible	Yes		
ROPS	Yes		

	Condition - Remarks	Parts	Labor
Horn	Very Good		
Parking Brake	Very Good		

GAUGES, OPERATOR STATION, CONSOLE

	Condition - Remarks	Parts	Labor
Dash Console	Very Good		
Meter	Very Good		
Gauges	Very Good		
Switches	Very Good		
Interior Lights	Poor		
Seat Cushion / Arm Rest	Good - air ride adj. button not working		
Floor Boards	Very Good		
EMS Panel / Warnings	Very Good		
Glass/Mirrors	Very Good		
Hydraulic Controls	Very Good		
Seat Belt	Very Good		

	Condition - Remarks	Parts	Labor
ROPS Certification Plate	Yes		
Back Up Alarm	Yes		

	Condition - Remarks	Parts	Labor
Fuel Level	very low		

ENGINE

	Condition - Remarks	Parts	Labor
Oil Leaks	No		
Blow By	No		
Knocking	No		
Compression in Radiator	No		
Water in Oil	No		
Fluid Levels OK?	Yes		

	Condition - Remarks	Parts	Labor
Anti-Freeze Color	red		

Oil Pressure (H/L/N)	normal		
Smoke (B/D/L/W)	black		

	Condition - Remarks	Parts	Labor
Operating Condition	Good		
Turbocharger / Blower	Good		
Fuel Injection System	Good		
Governor	Good		
Engine Supports	Good		
Air Cleaners	Poor		
Exhaust / Muffler	Good		
Belts / Pulleys	Good		

COOLING SYSTEM

	Condition - Remarks	Parts	Labor
Radiator	Fair - low level		
Coolers	Good		
Hoses	Good		
Water Pump	Good		
Fan	Good		
Fan Drive	Good		

	Condition - Remarks	Parts	Labor
Leaks	No - non seen but radiator level low and surge tank empty		

ELECTRICAL, STARTING AND CHARGING SYSTEM

	Condition - Remarks	Parts	Labor
Batteries / Cables	Good		
Starter	Good		
Alternator	Good		
Wiring	Good		
Pre-Heater	Good		
Lighting	Good		

TANDEM/GEARS/BEARINGS/CHAINS

	Condition - Remarks	Parts	Labor
Front Axle	Good		
Rear Axle	Good		
Travel Motors	Good		
Travel Pumps	Good		
Travel Controls	Good		
Lines / Linkages	Good		
Operating Condition	Good		

HYDRAULICS

	Condition - Remarks	Parts	Labor
Operating Condition	Good		
Tank	Good		
Pumps & Valves	Good		
Hose Lines	Good		
Tilt Cylinder	Good		
Lift Cylinders	Good		

	Condition - Remarks	Parts	Labor
Leaks	No		

————— BUCKET —————

	Condition - Remarks	Parts	Labor
Cutting Edges	Good		
Bucket Bottom	Good		
Bucket Sides	Good		
Bucket Linkage	Good		
Loader Pins & Bushings	Good		
Loader Frame	Good		
Quick Coupler	Good		

————— TIRES —————

	Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Right Front	caterpillar	20		No	No	No
Left Front		21		No	No	No
Right Rear		21		No	No	No
Left Rear		20		No	No	No
Tire Size	12 - 16.6 nhs					

Photos

Click thumbnails to enlarge.





Caterpillar Confidential: Green. Copyright © 2009, Caterpillar Inc. All Rights Reserved.