

## SPECIFICATIONS

2006 CATERPILLAR 305CCR

Customer Owned Certified

**TRACK EXCAVATORS**

Inspection Number:	647919	Serial #:	HWJ01106
Date Created:	05/21/2009 09:20:30 AM CDT	Engine Serial #:	N/A
Last Updated:	05/21/2009 09:31:07 AM CDT	Transmission Serial #:	N/A
Originated By:	Samy Cashio	SMU/Hrs:	663
Inspector:	N/A	Last Scheduled Oil Sample:	N/A
Reviewer:	N/A	Last Cat Track System Inspection:	N/A
Salesman:	N/A	Last Preventative Maintenance:	N/A
Location:	HOUSTON, Texas, United States	Recommendation:	no recommendation
Asking Price:	N/A	Final Price:	N/A

## Client

Name: Louisiana Machinery

City: RESERVE

State: Louisiana

Country: United States

## Description

1.) Machine was last serviced on 12/12/08 at 457 Hours. (500 HR. PM.) 2.) Some minor dents to leveling blade (But is ok) 3.) Rubber Tracks U/C-Some minor chunks in rubber tracks.

## Features

- BLADE, LEVELING
- BOOM, 1 PIECE
- STICK, MEDIUM
- CARBODY, STANDARD
- AUXILIARY HYDRAULICS

## Condition

## GENERAL APPEARANCE

	Condition - Remarks	Parts	Labor
Radiator Grill & Shroud	Good		
Eng. Enclose Hood / Stack	Good		
Fuel Tank	Good		
Crankcase Guard / Battery Box	Good		
Main Frame Welds	Very Good		
Car Body	Good		
Steps / Ladder	Good		
Grab Irons	Good		

Paint	Good		
Hood	Good		
Sheet Metal	Good		

	Condition - Remarks	Parts	Labor
S.O.S. Taken	No		
Cleaning Required	No		

———— SAFETY ITEMS ————

	Condition - Remarks	Parts	Labor
ROPS	Yes - ROPS		
Safety Decals In Place	Yes		
Safety Decals Legible	Yes		

	Condition - Remarks	Parts	Labor
Horn	Good		
Brake Hold	Good		
Swing Brake	Good		

———— GAUGES, OPERATOR STATION, CONSOLE ————

	Condition - Remarks	Parts	Labor
Gauges	Good		
Switches	Good		
Dash Console	Good		
Meter	Good		
Seat Cushion / Arm Rest	Good		
Floor Boards	Good		
EMS Panel / Warnings	Good		
Glass/Mirrors	Good - Mirrors		
Seat Belt	Good		

	Condition - Remarks	Parts	Labor
ROPS Certification Plate	Yes		
Back Up Alarm	Yes		

———— ENGINE ————

	Condition - Remarks	Parts	Labor
Oil Leaks	No		
Blow By	No		
Knocking	No		
Compression in Radiator	No - Normal Circulation		
Water in Oil	No		
Fluid Levels OK?	Yes		

	Condition - Remarks	Parts	Labor
Anti-Freeze Color	Red		

Oil Pressure (H/L/N)	Normal		
Smoke (B/D/L/W)	Light		

	Condition - Remarks	Parts	Labor
Operating Condition	Good		
Air Cleaners	Good		
Governor	Good		
Turbocharger / Blower	Good		
Fuel Injection System	Good		
Engine Supports	Good		
Oil Filter Condition (CUT)	Good - DID NOT CUT		
Belts / Pulleys	Good		
Exhaust / Muffler	Good		

————— COOLING SYSTEM —————

	Condition - Remarks	Parts	Labor
Water Pump	Good		
Fan	Good		
Hoses	Good		
Radiator	Good		
Coolers	Good		
Fan Drive	Good		

	Condition - Remarks	Parts	Labor
Leaks	No		

————— ELECTRICAL, STARTING AND CHARGING SYSTEM —————

	Condition - Remarks	Parts	Labor
Batteries / Cables	Very Good		
Starter	Very Good		
Alternator	Very Good		
Wiring	Very Good		
Lighting	Very Good - All lights are working		

————— FINAL DRIVES —————

	Condition - Remarks	Parts	Labor
Planetaries / Diff	Good		
Housings	Good		

————— HYDRAULICS —————

	Condition - Remarks	Parts	Labor
Operating Condition	Good		
Pump Drive	Good		
Pumps & Valves	Good		
Boom Cylinder	Good		
Bucket Cylinder	Good		

Stick Cylinder	Good		
Hose Lines	Good		
Control Linkage	Good		
Swing Gear	Good		
Tank	Good		
Swing Motors	Good		
Travel Motors	Good		
Hydraulic Swivel	Good		
Filter Condition (CUT)	Good - DID NOT CUT		

	Condition - Remarks	Parts	Labor
Swing Drive Oil Level	ok		

————— BOOM —————

	Condition - Remarks	Parts	Labor
Pins & Bushings	Good		
Boom Condition	Good		
Boom Pins	Good		

————— STICK —————

	Condition - Remarks	Parts	Labor
Pins & Bushings	Good		
Stick Conditions	Good		
Stick Pins	Good		

	Condition - Remarks	Parts	Labor
Stick Length	Standard Stick		

————— BUCKET —————

	Condition - Remarks	Parts	Labor
Cutting Edges	Good		
Teeth / Adapters	Good		
Bucket Bottom	Good		
Bucket Sides	Good		
Bucket Linkage	Good - Some minor wear side to side (normal wear indicative of hours, could use shims)		
Bucket Mounts	Good		
Notes	24" Digging Bucket with Teeth and Welded on Edge		

	Condition - Remarks	Parts	Labor
Width	24"		

————— UNDERCARRIAGE —————

	Condition - Remarks	Parts	Labor
Track Frame - Left	Good		
Track Frame - Right	Good		
Notes	Has Rubber Tracks that are in good condition, Some minor chunks are taken out of rubber tracks.		

