

[«Back to Inspection Results](#)**MUSTANG CAT****SPECIFICATIONS****2005 CATERPILLAR 268B****Customer Owned Certified****SKID STEER LOADERS**

<b>Inspection Number:</b>	646118	<b>Serial #:</b>	LBA00813
<b>Date Created:</b>	05/06/2009 09:55:51 AM CDT	<b>Engine Serial #:</b>	N/A
<b>Last Updated:</b>	05/06/2009 10:00:53 AM CDT	<b>Transmission Serial #:</b>	N/A
<b>Originated By:</b>	John King	<b>SMU/Hrs:</b>	3230
<b>Inspector:</b>	John King	<b>Last Scheduled Oil Sample:</b>	N/A
<b>Reviewer:</b>	N/A	<b>Last Cat Track System Inspection:</b>	N/A
<b>Salesman:</b>	John King	<b>Last Preventative Maintenance:</b>	N/A
<b>Location:</b>	HOUSTON, Texas, United States	<b>Recommendation:</b>	no recommendation
<b>Asking Price:</b>	N/A	<b>Final Price:</b>	N/A

**Client****Name:** MustangCat**City:** Houston  
**State:** Texas  
**Country:** United States**Features**

- OROPS
- HIGH FLOW HYDRAULICS
- SELF LEVELING

**Condition****GENERAL APPEARANCE**

	Condition - Remarks	Parts	Labor
Eng. Enclose Hood / Stack	Good		
Fenders	Good		
Fuel Tank	Good		
Crankcase Guard / Battery Box	Good		
Main Frame Welds	Good		
Bumper	Good		
Pre-Cleaner Bowl	Good		
Cab or Canopy	Fair - slightly dent		
Steps / Ladder	Fair		
Grab Irons	Fair - bent		
Paint	Fair		
Sheet Metal	Good		

	Condition - Remarks	Parts	Labor
S.O.S. Taken	No		
Cleaning Required	No		

**SAFETY ITEMS**

	Condition - Remarks	Parts	Labor
Safety Decals Legible	No		
ROPS	No		

	Condition - Remarks	Parts	Labor
Horn	Good		
Parking Brake	Good		

**GAUGES, OPERATOR STATION, CONSOLE**

	Condition - Remarks	Parts	Labor
Dash Console	Good		
Meter	Good		
Gauges	Good		
Switches	Good		
Interior Lights	Good		
Seat Cushion / Arm Rest	Fair - seat torn		
Floor Boards	Good		
EMS Panel / Warnings	Good		
Glass/Mirrors	Poor - missing mirror		
Hydraulic Controls	Good		
Seat Belt	Good		

	Condition - Remarks	Parts	Labor
Current Parts Manual	No		
Current Safety Manual	No		
Current O&MM	No		
ROPS Certification Plate	No		
Back Up Alarm	Yes		

**ENGINE**

	Condition - Remarks	Parts	Labor
Oil Leaks	No		
Blow By	No		
Knocking	No		
Compression in Radiator	No		
Water in Oil	No		
Fluid Levels OK?	Yes		

	Condition - Remarks	Parts	Labor
Operating Condition	Good		
Turbocharger / Blower	Good		
Fuel Injection	Good		

<b>System</b>			
<b>Governor</b>	Good		
<b>Engine Supports</b>	Good		
<b>Air Cleaners</b>	Good		
<b>Exhaust / Muffler</b>	Good		
<b>Belts / Pulleys</b>	Good		
<b>Oil Filter Condition (CUT)</b>	Good		

**————— COOLING SYSTEM —————**

	<b>Condition - Remarks</b>	<b>Parts</b>	<b>Labor</b>
<b>Radiator</b>	Good		
<b>Coolers</b>	Good		
<b>Hoses</b>	Good		
<b>Water Pump</b>	Good		
<b>Fan</b>	Good		
<b>Fan Drive</b>	Good		

	<b>Condition - Remarks</b>	<b>Parts</b>	<b>Labor</b>
<b>Leaks</b>	No		

**————— ELECTRICAL, STARTING AND CHARGING SYSTEM —————**

	<b>Condition - Remarks</b>	<b>Parts</b>	<b>Labor</b>
<b>Batteries / Cables</b>	Good		
<b>Starter</b>	Good		
<b>Alternator</b>	Good		
<b>Wiring</b>	Good		
<b>Pre-Heater</b>	Good		
<b>Lighting</b>	Good		

**————— TANDEM/GEARS/BEARINGS/CHAINS —————**

	<b>Condition - Remarks</b>	<b>Parts</b>	<b>Labor</b>
<b>Front Axle</b>	Good		
<b>Rear Axle</b>	Good		
<b>Travel Motors</b>	Good		
<b>Travel Pumps</b>	Good		
<b>Travel Controls</b>	Good		
<b>Lines / Linkages</b>	Good		
<b>Operating Condition</b>	Good		

**————— HYDRAULICS —————**

	<b>Condition - Remarks</b>	<b>Parts</b>	<b>Labor</b>
<b>Operating Condition</b>	Good		
<b>Tank</b>	Good		
<b>Pumps &amp; Valves</b>	Good		
<b>Hose Lines</b>	Good		
<b>Detent Switch</b>	Good		

Tilt Cylinder	Good		
Lift Cylinders	Good		
Filter Condition (CUT)	Good		

	Condition - Remarks	Parts	Labor
Leaks	No		

**————— BUCKET —————**

	Condition - Remarks	Parts	Labor
Cutting Edges	Fair		
Teeth / Adapters	Fair		
Bucket Bottom	Fair		
Bucket Sides	Fair		
Loader Pins & Bushings	Good		
Loader Frame	Good		
Quick Coupler	Good		
Multi Purpose Cylinders	Good		
Notes	72 GP		

**————— TIRES —————**

	Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Right Front			90			
Left Front			90			
Right Rear			90			
Left Rear			90			

**Photos**

Click thumbnails to enlarge.





Caterpillar Confidential: Green. Copyright © 2009, Caterpillar Inc. All Rights Reserved.