

SPECIFICATIONS

2006 CATERPILLAR 277B

Customer Owned Certified

MULTI TERRAIN LOADERS

Inspection Number:	647912	Serial #:	MDH03298
Date Created:	05/21/2009 09:05:52 AM CDT	Engine Serial #:	N/A
Last Updated:	05/21/2009 09:14:17 AM CDT	Transmission Serial #:	N/A
Originated By:	Samy Cashio	SMU/Hrs:	1148
Inspector:	N/A	Last Scheduled Oil Sample:	N/A
Reviewer:	N/A	Last Cat Track System Inspection:	N/A
Salesman:	N/A	Last Preventative Maintenance:	N/A
Location:	HOUSTON, Texas, United States	Recommendation:	no recommendation
Asking Price:	N/A	Final Price:	N/A

Client

Name: Louisiana Machinery

City: RESERVE
 State: Louisiana
 Country: United States

Description

1.) Machine was last serviced on 4/11/09 at 1131 Hours. (250 HR. PM.)

Features

- OROPS
- BUCKET
- SELF LEVELING

Condition

————— GENERAL APPEARANCE —————

	Condition - Remarks	Parts	Labor
Radiator Grill & Shroud	Good		
Eng. Enclose Hood / Stack	Good		
Fuel Tank	Good		
Crankcase Guard / Battery Box	Good		
Main Frame Welds	Very Good		
Cab or Canopy	Very Good - Canopy		
Steps / Ladder	Very Good		
Grab Irons	Very Good		
Paint	Good		
Sheet Metal	Good		

	Condition - Remarks	Parts	Labor
S.O.S. Taken	No		
Cleaning Required	No		

———— SAFETY ITEMS ————

	Condition - Remarks	Parts	Labor
Safety Decals In Place	Yes		
Safety Decals Legible	Yes		
ROPS	Yes - ROPS		

	Condition - Remarks	Parts	Labor
Horn	Very Good		
Parking Brake	Very Good		

———— GAUGES, OPERATOR STATION, CONSOLE ————

	Condition - Remarks	Parts	Labor
Dash Console	Good		
Meter	Good		
Gauges	Good		
Switches	Good		
Interior Lights	Good		
Seat Cushion / Arm Rest	Very Good		
Floor Boards	Very Good		
EMS Panel / Warnings	Very Good		
Glass/Mirrors	Very Good - One Mirror and Rear Glass		
Hydraulic Controls	Very Good		

	Condition - Remarks	Parts	Labor
ROPS Certification Plate	Yes		
Back Up Alarm	Yes		

———— ENGINE ————

	Condition - Remarks	Parts	Labor
Oil Leaks	No		
Blow By	No		
Knocking	No		
Compression in Radiator	No - Normal Circulation		
Water in Oil	No		
Fluid Levels OK?	Yes		

	Condition - Remarks	Parts	Labor
Anti-Freeze Color	Red		
Oil Pressure (H/L/N)	Normal		

Smoke (B/D/L/W)	Black		
-----------------	-------	--	--

	Condition - Remarks	Parts	Labor
Operating Condition	Good		
Turbocharger / Blower	Good		
Fuel Injection System	Good		
Governor	Good		
Engine Supports	Good		
Air Cleaners	Good		
Exhaust / Muffler	Good		
Belts / Pulleys	Good		
Oil Filter Condition (CUT)	Good - DID NOT CUT		

————— COOLING SYSTEM —————

	Condition - Remarks	Parts	Labor
Radiator	Good		
Coolers	Good		
Hoses	Good		
Water Pump	Good		
Fan	Good		
Fan Drive	Good		

	Condition - Remarks	Parts	Labor
Leaks	No		

————— ELECTRICAL, STARTING AND CHARGING SYSTEM —————

	Condition - Remarks	Parts	Labor
Batteries / Cables	Very Good		
Starter	Very Good		
Alternator	Very Good		
Wiring	Very Good		
Lighting	Very Good - All lights are working (Front and Rear)		

————— TANDEM/GEARS/BEARINGS/CHAINS —————

	Condition - Remarks	Parts	Labor
Front Axle	Good		
Rear Axle	Good		
Travel Motors	Good		
Travel Pumps	Good		
Travel Controls	Good		
Lines / Linkages	Good		
Operating Condition	Good		

————— HYDRAULICS —————

	Condition - Remarks	Parts	Labor
Operating Condition	Good		

Tank	Good		
Pump & Valves	Good		
Hoses / Lines	Good		
Tilt Cylinder	Good		
Lift Cylinders	Good		
Filter Condition (CUT)	Good - DID NOT CUT		

	Condition - Remarks	Parts	Labor
Leaks	No		

———— ATTACHMENTS / WORK TOOLS ————

	Condition - Remarks	Parts	Labor
Operating Condition	Good		

	Condition - Remarks	Parts	Labor
Other	Front Grapple Bucket		

———— BUCKET ————

	Condition - Remarks	Parts	Labor
Cutting Edges	Good		
Bucket Bottom	Good		
Bucket Sides	Good		
Bucket Linkage	Good		
Loader Pins & Bushings	Good		
Loader Frame	Good		
Quick Coupler	Good - Manual		
Multi Purpose Cylinders	Good		
Notes	Front Grapple Bucket		

———— UNDERCARRIAGE ————

	Condition - Remarks	Parts	Labor
Roller	Good		
Track / Belt Condition	Good		
Roller Frame	Good		
Idlers	Good		
Sprocket	Good		
Notes	Has 18" Rubber Tracks-All Components are in very good condition.		

	Condition - Remarks	Parts	Labor
Track / Belt Width	18"		