

**Louisiana
Machinery**

SPECIFICATIONS
2007 CATERPILLAR 277B
Customer Owned Certified
MULTI TERRAIN LOADERS

Inspection Number: 647450	Serial #: MDH05135
Date Created: 05/18/2009 01:08:20 PM CDT	Engine Serial #: N/A
Last Updated: 05/19/2009 12:18:18 PM CDT	Transmission Serial #: N/A
Originated By: Samy Cashio	SMU/Hrs: 1257
Inspector: N/A	Last Scheduled Oil Sample: N/A
Reviewer: N/A	Last Cat Track System Inspection: N/A
Salesman: N/A	Last Preventative Maintenance: N/A
Location: HOUSTON, Texas, United States	Recommendation: no recommendation
Asking Price: N/A	Final Price: N/A

Client
Name: Louisiana Machinery

City: RESERVE
State: Louisiana
Country: United States

Description

1.) Machine was last serviced on 4/22/09 at 1256 Hours. (250 HR. PM.) 2.) Bucket Edge could use a turn. 3.) Step at bucket is slightly bent. (but is ok)

Features

- EROPS
- AIR CONDITIONER
- HEATER
- BUCKET
- AUXILIARY HYDRAULICS
- SELF LEVELING

Condition
GENERAL APPEARANCE

	Condition - Remarks	Parts	Labor
Radiator Grill & Shroud	Good		
Eng. Enclose Hood / Stack	Good		
Fuel Tank	Good		
Crankcase Guard / Battery Box	Good		
Main Frame Welds	Very Good		
Cab or Canopy	Good		
Steps / Ladder	Good - One bent step on top of bucket (but is ok)		
Grab Irons	Good		
Paint	Good		
Sheet Metal	Good		

	Condition - Remarks	Parts	Labor
S.O.S. Taken	No		
Cleaning Required	No		

SAFETY ITEMS

	Condition - Remarks	Parts	Labor
Safety Decals In Place	Yes		
Safety Decals Legible	Yes		
ROPS	Yes - ROPS		

	Condition - Remarks	Parts	Labor
Horn	Good		
Parking Brake	Good		

GAUGES, OPERATOR STATION, CONSOLE

	Condition - Remarks	Parts	Labor
Dash Console	Good		
Meter	Good		
Gauges	Good		
Switches	Good		
Windshield Wipers	Good		
Heater	Good		
Interior Lights	Good		
Seat Cushion / Arm Rest	Good		
Floor Boards	Good		
EMS Panel / Warnings	Good		
Door Latches	Good		
Glass/Mirrors	Good		
Hydraulic Controls	Good		
Air Conditioner	Good - Blows Cold		

	Condition - Remarks	Parts	Labor
ROPS Certification Plate	Yes		
Back Up Alarm	Yes		

ENGINE

	Condition - Remarks	Parts	Labor
Oil Leaks	No		
Blow By	No		
Knocking	No		
Compression in Radiator	No - Normal Circulation		
Water in Oil	No		
Fluid Levels OK?	Yes		

	Condition - Remarks	Parts	Labor
Operating Condition	Good		
Turbocharger /			

Blower	Good		
Fuel Injection System	Good		
Governor	Good		
Engine Supports	Good		
Air Cleaners	New - New Air Filter		
Exhaust / Muffler	Good		
Belts / Pulleys	Good		
Oil Filter Condition (CUT)	Good - DID NOT CUT		

————— COOLING SYSTEM —————

	Condition - Remarks	Parts	Labor
Radiator	Good		
Coolers	Good		
Hoses	Good		
Water Pump	Good		
Fan	Good		
Fan Drive	Good		

	Condition - Remarks	Parts	Labor
Leaks	No		

————— ELECTRICAL, STARTING AND CHARGING SYSTEM —————

	Condition - Remarks	Parts	Labor
Batteries / Cables	Very Good		
Starter	Very Good		
Alternator	Very Good		
Wiring	Very Good		
Lighting	Very Good - All lights are working		

————— TANDEM/S/GEARS/BEARINGS/CHAINS —————

	Condition - Remarks	Parts	Labor
Front Axle	Good		
Rear Axle	Good		
Travel Motors	Good		
Travel Pumps	Good		
Travel Controls	Good		
Lines / Linkages	Good		
Operating Condition	Good		

————— HYDRAULICS —————

	Condition - Remarks	Parts	Labor
Operating Condition	Good		
Tank	Good		
Pump & Valves	Good		
Hoses / Lines	Good		
Detent Switch	Good		
Tilt Cylinder	Good		
Lift Cylinders	Good		

Filter Condition (CUT)	Good - DID NOT CUT		
-------------------------------	--------------------	--	--

	Condition - Remarks	Parts	Labor
Leaks	No		

———— BUCKET ————

	Condition - Remarks	Parts	Labor
Cutting Edges	Fair - Bucket edges could use a turn		
Bucket Bottom	Good		
Bucket Sides	Good		
Bucket Linkage	Good		
Loader Pins & Bushings	Good		
Loader Frame	Good		
Quick Coupler	Good - Manual		
Notes	General Purpose Bucket with Bolt on Edge		

———— UNDERCARRIAGE ————

	Condition - Remarks	Parts	Labor
Roller	Good		
Track / Belt Condition	Good		
Roller Frame	Good		
Idlers	Good		
Sprocket	Good		
Notes	18" Rubber Tracks, Tracks are a bit worn and rollers have some chunks taken out.		