

[«Back to Inspection Results](#)**MUSTANG** **SPECIFICATIONS****2004 CATERPILLAR 226B****Customer Owned Certified****SKID STEER LOADERS**

Inspection Number:	648978	Serial #:	MJH01937
Date Created:	05/29/2009 01:01:03 PM CDT	Engine Serial #:	N/A
Last Updated:	05/29/2009 01:10:09 PM CDT	Transmission Serial #:	N/A
Originated By:	DOUGLAS HARRISON	SMU/Hrs:	668
Inspector:	DOUGLAS HARRISON	Last Scheduled Oil Sample:	N/A
Reviewer:	N/A	Last Cat Track System Inspection:	N/A
Salesman:	N/A	Last Preventative Maintenance:	12/08/2008
Location:	HOUSTON, Texas, United States	Recommendation:	no recommendation
Asking Price:	N/A	Final Price:	N/A

Client

Name: n/a n/a
Company: Warren Cat

State: Unknown
Country: [Not Specified]

Description

Auction Machine

Features

- OROPS
- BUCKET
- HYDRAULICS, STANDARD FLOW

Condition**GENERAL APPEARANCE**

	Condition - Remarks	Parts	Labor
Radiator Grill & Shroud	Good		
Eng. Enclose Hood / Stack	Good		
Fenders	Good		
Fuel Tank	Good		
Crankcase Guard / Battery Box	Good		
Main Frame Welds	Good		
Bumper	Good		
Cab or Canopy	Good		
Steps / Ladder	Good		
Grab Irons	Good - minor bend on left one		
Paint	Good		
Sheet Metal	Good		

	Condition - Remarks	Parts	Labor
S.O.S. Taken	No		
Cleaning Required	No		

SAFETY ITEMS

	Condition - Remarks	Parts	Labor
Safety Decals In Place	Yes		
Safety Decals Legible	Yes		
ROPS	Yes		

	Condition - Remarks	Parts	Labor
Horn	Very Good		
Parking Brake	Very Good		

GAUGES, OPERATOR STATION, CONSOLE

	Condition - Remarks	Parts	Labor
Dash Console	Good		
Meter	Good		
Gauges	Good		
Interior Lights	Good		
Seat Cushion / Arm Rest	Fair - split cushion		
Floor Boards	Good		
EMS Panel / Warnings	Good		
Glass/Mirrors	Good		
Hydraulic Controls	Good		
Seat Belt	Good		

	Condition - Remarks	Parts	Labor
ROPS Certification Plate	Yes		
Back Up Alarm	Yes		

	Condition - Remarks	Parts	Labor
Fuel Level	1/4		

ENGINE

	Condition - Remarks	Parts	Labor
Oil Leaks	Yes - coming out exhaust pipe		
Blow By	No		
Knocking	No		
Compression in Radiator	No		
Water in Oil	No		
Fluid Levels OK?	Yes		

	Condition - Remarks	Parts	Labor
Anti-Freeze Color	red		
Oil Pressure			

(H/L/N)	normal		
Smoke (B/D/L/W)	black at start up. blue after that		

	Condition - Remarks	Parts	Labor
Operating Condition	Good		
Turbocharger / Blower	Poor - leaking oil		
Fuel Injection System	Good		
Governor	Good		
Engine Supports	Good		
Air Cleaners	Poor		
Exhaust / Muffler	Good		
Belts / Pulleys	Fair - loose		

COOLING SYSTEM

	Condition - Remarks	Parts	Labor
Radiator	Good		
Coolers	Good		
Hoses	Good		
Water Pump	Good		
Fan	Good		
Fan Drive	Good		

	Condition - Remarks	Parts	Labor
Leaks	No		

ELECTRICAL, STARTING AND CHARGING SYSTEM

	Condition - Remarks	Parts	Labor
Batteries / Cables	Good		
Starter	Good		
Alternator	Good		
Wiring	Good		
Pre-Heater	Good		
Lighting	Good - tail lights out		

TANDEMS/GEARS/BEARINGS/CHAINS

	Condition - Remarks	Parts	Labor
Front Axle	Good		
Rear Axle	Good		
Travel Motors	Good		
Travel Pumps	Good		
Travel Controls	Good		
Lines / Linkages	Good		
Operating Condition	Good		

HYDRAULICS

	Condition - Remarks	Parts	Labor

Operating Condition	Good		
Tank	Good		
Pumps & Valves	Good		
Hose Lines	Good		
Tilt Cylinder	Good		
Lift Cylinders	Good		

	Condition - Remarks	Parts	Labor
Leaks	No		

————— BUCKET —————

	Condition - Remarks	Parts	Labor
Cutting Edges	Good		
Bucket Bottom	Good		
Bucket Sides	Good		
Bucket Linkage	Good		
Loader Pins & Bushings	Fair - loose at bucket pins		
Loader Frame	Good		

————— TIRES —————

	Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Right Front	caterpillar	22		No	No	No
Left Front		22		No	No	No
Right Rear		23		No	No	No
Left Rear		22		No	No	No
Tire Size	10-16.5 nhs					

Caterpillar Confidential: Green. Copyright © 2009, Caterpillar Inc. All Rights Reserved.