

[Delete](#)[«Back to Inspection Results](#)**MUSTANG** **SPECIFICATIONS****2006 CATERPILLAR 247B****Customer Owned Certified****MULTI TERRAIN LOADERS**

Inspection Number:	646399	Serial #:	MTL02813
Date Created:	05/08/2009 10:55:44 AM CDT	Engine Serial #:	N/A
Last Updated:	05/08/2009 01:48:30 PM CDT	Transmission Serial #:	N/A
Originated By:	John King	SMU/Hrs:	967
Inspector:	John King	Last Scheduled Oil Sample:	N/A
Reviewer:	N/A	Last Cat Track System Inspection:	N/A
Salesman:	John King	Last Preventative Maintenance:	N/A
Location:	HOUSTON, Texas, United States	Recommendation:	no recommendation
Asking Price:	N/A	Final Price:	N/A

Client**Name:** MustangCat**City:** Houston**State:** Texas**Country:** United States**Features**

- OROPS
- BUCKET
- HYDRAULICS, STANDARD FLOW
- SELF LEVELING

Condition**GENERAL APPEARANCE**

	Condition - Remarks	Parts	Labor
Radiator Grill & Shroud	Good		
Eng. Enclose Hood / Stack	Good		
Fenders	Good		
Fuel Tank	Good		
Crankcase Guard / Battery Box	Good		
Main Frame Welds	Good		
Bumper	Good		
Pre-Cleaner Bowl	Good		
Cab or Canopy	Fair - mirror missing		
Steps / Ladder	Fair		
Grab Irons	Fair		
Paint	Fair		
Sheet Metal	Fair		

	Condition - Remarks	Parts	Labor
S.O.S. Taken	No		
Cleaning Required	No		

SAFETY ITEMS

	Condition - Remarks	Parts	Labor
Safety Decals In Place	No		
Safety Decals Legible	No		
ROPS	No		

	Condition - Remarks	Parts	Labor
Horn	Good		
Parking Brake	Good		

GAUGES, OPERATOR STATION, CONSOLE

	Condition - Remarks	Parts	Labor
Dash Console	Good		
Meter	Good		
Gauges	Good		
Switches	Good		
Seat Cushion / Arm Rest	Good		
Floor Boards	Good		
Glass/Mirrors	Fair - missing mirror		
Hydraulic Controls	Good		
Air Conditioner	Good		

	Condition - Remarks	Parts	Labor
Back Up Alarm	Yes		

ENGINE

	Condition - Remarks	Parts	Labor
Oil Leaks	No		
Blow By	No		
Knocking	No		
Compression in Radiator	No		
Water in Oil	No		
Fluid Levels OK?	Yes		
EPA Decal	No		

	Condition - Remarks	Parts	Labor
Operating Condition	Good		
Turbocharger / Blower	Good		
Fuel Injection System	Good		
Governor	Good		
Engine Supports	Good		

Air Cleaners	Good		
Exhaust / Muffler	Good		
Oil Filter Condition (CUT)	Good		

————— COOLING SYSTEM —————

	Condition - Remarks	Parts	Labor
Radiator	Good		
Coolers	Good		
Hoses	Good		
Water Pump	Good		
Fan	Good		
Fan Drive	Good		

	Condition - Remarks	Parts	Labor
Leaks	No		

————— ELECTRICAL, STARTING AND CHARGING SYSTEM —————

	Condition - Remarks	Parts	Labor
Batteries / Cables	Good		
Starter	Good		
Alternator	Good		
Wiring	Good		
Pre-Heater	Good		
Lighting	Good		

————— TANDEM/S/GEARS/BEARINGS/CHAINS —————

	Condition - Remarks	Parts	Labor
Front Axle	Good		
Rear Axle	Good		
Travel Motors	Good		
Travel Pumps	Good		
Travel Controls	Good		
Lines / Linkages	Good		
Operating Condition	Good		

————— HYDRAULICS —————

	Condition - Remarks	Parts	Labor
Operating Condition	Good		
Tank	Good		
Pump & Valves	Good		
Hoses / Lines	Good		
Detent Switch	Good		
Tilt Cylinder	Good		
Lift Cylinders	Good		
Filter Condition (CUT)	Good		

	Condition - Remarks	Parts	Labor
Leaks	No		

ATTACHMENTS / WORK TOOLS

	Condition - Remarks	Parts	Labor
Operating Condition	Good		

BUCKET

	Condition - Remarks	Parts	Labor
Cutting Edges	Very Good		
Teeth / Adapters	Very Good		
Bucket Bottom	Very Good		
Bucket Sides	Very Good		
Bucket Linkage	Good		
Loader Pins & Bushings	Good		
Loader Frame	Good		
Quick Coupler	Good		
Multi Purpose Cylinders	Good		

UNDERCARRIAGE

	Condition - Remarks	Parts	Labor
Roller	Good		
Track / Belt Condition	Good		
Roller Frame	Good		
Idlers	Good		
Sprocket	Good		

	Condition - Remarks	Parts	Labor
% Worn	new tracks		

Caterpillar Confidential: Green. Copyright © 2009, Caterpillar Inc. All Rights Reserved.