

[«Back to Inspection Results](#)**MUSTANG** **SPECIFICATIONS****2006 CATERPILLAR 247B****Customer Owned Certified****MULTI TERRAIN LOADERS**

Inspection Number:	646257	Serial #:	MTL03329
Date Created:	05/07/2009 10:22:59 AM CDT	Engine Serial #:	N/A
Last Updated:	05/07/2009 10:29:37 AM CDT	Transmission Serial #:	N/A
Originated By:	Jan Oswald	SMU/Hrs:	1403
Inspector:	Jan Oswald	Last Scheduled Oil Sample:	N/A
Reviewer:	N/A	Last Cat Track System Inspection:	N/A
Salesman:	N/A	Last Preventative Maintenance:	N/A
Location:	Texas, United States	Recommendation:	no recommendation
Asking Price:	N/A	Final Price:	N/A

Features

- BUCKET

Condition**GENERAL APPEARANCE**

	Condition - Remarks	Parts	Labor
Radiator Grill & Shroud	Good		
Eng. Enclose Hood / Stack	Good		
Fenders	Good		
Fuel Tank	Good		
Crankcase Guard / Battery Box	Good		
Main Frame Welds	Good		
Bumper	Good		
Counterweight	Good		
Steps / Ladder	Good		
Grab Irons	Good		
Paint	Good		
Sheet Metal	Good		

	Condition - Remarks	Parts	Labor
S.O.S. Taken	Yes		
Cleaning Required	No		

SAFETY ITEMS

	Condition - Remarks	Parts	Labor
ROPS	Yes		

	Condition - Remarks	Parts	Labor
--	---------------------	-------	-------

Horn	Good		
Parking Brake	Good		

GAUGES, OPERATOR STATION, CONSOLE

	Condition - Remarks	Parts	Labor
Dash Console	Good		
Meter	Good		
Gauges	Good		
Switches	Good		
Seat Cushion / Arm Rest	Good		
Floor Boards	Good		
EMS Panel / Warnings	Good		
Door Latches	Good		
Glass/Mirrors	Good		

	Condition - Remarks	Parts	Labor
Current Safety Manual	Yes		
Current O&MM	Yes		
Back Up Alarm	Yes		

ENGINE

	Condition - Remarks	Parts	Labor
Oil Leaks	No		
Blow By	No		
Knocking	No		
Compression in Radiator	No		
Water in Oil	No		
Fluid Levels OK?	Yes		

	Condition - Remarks	Parts	Labor
Anti-Freeze Color	Red		
Oil Pressure (H/L/N)	Normal		
Smoke (B/D/L/W)	Normal		

	Condition - Remarks	Parts	Labor
Air Cleaners	Good		
Exhaust / Muffler	Good		
Belts / Pulleys	Good		

COOLING SYSTEM

	Condition - Remarks	Parts	Labor
Radiator	Good		
Hoses	Good		

ELECTRICAL, STARTING AND CHARGING SYSTEM

--	--	--	--

	Condition - Remarks	Parts	Labor
Batteries / Cables	Good		
Starter	Good		
Alternator	Good		
Wiring	Good		
Pre-Heater	Good		
Lighting	Good		

TANDEM/GEARS/BEARINGS/CHAINS

	Condition - Remarks	Parts	Labor
Travel Motors	Good		
Travel Pumps	Good		
Travel Controls	Good		
Lines / Linkages	Good		
Operating Condition	Good		

HYDRAULICS

	Condition - Remarks	Parts	Labor
Operating Condition	Good		
Tank	Good		
Pump & Valves	Good		
Hoses / Lines	Good		
Detent Switch	Good		
Lift Cylinders	Good		
Filter Condition (CUT)	Good		

	Condition - Remarks	Parts	Labor
Leaks	No		

ATTACHMENTS / WORK TOOLS

	Condition - Remarks	Parts	Labor
Operating Condition	Good		

BUCKET

	Condition - Remarks	Parts	Labor
Cutting Edges	Good		
Bucket Bottom	Good		
Bucket Sides	Good		
Bucket Linkage	Good		
Loader Pins & Bushings	Good		
Loader Frame	Good		
Quick Coupler	Good		

	Condition - Remarks	Parts	Labor
Bucket Capacity	60ln (.47yd-3)		

Bucket S/N	65SSGPD10910		
-------------------	--------------	--	--

Caterpillar Confidential: Green. Copyright © 2009, Caterpillar Inc. All Rights Reserved.