

[«Back to Inspection Results](#)**MUSTANG** **SPECIFICATIONS****2005 CATERPILLAR 246B****Customer Owned Certified****SKID STEER LOADERS**

Inspection Number:	649008	Serial #:	PAT02285
Date Created:	05/29/2009 03:26:09 PM CDT	Engine Serial #:	N/A
Last Updated:	05/29/2009 03:39:09 PM CDT	Transmission Serial #:	N/A
Originated By:	DOUGLAS HARRISON	SMU/Hrs:	1322
Inspector:	DOUGLAS HARRISON	Last Scheduled Oil Sample:	N/A
Reviewer:	N/A	Last Cat Track System Inspection:	N/A
Salesman:	N/A	Last Preventative Maintenance:	06/20/2007
Location:	HOUSTON, Texas, United States	Recommendation:	no recommendation
Asking Price:	N/A	Final Price:	N/A

Client

Name: n/a n/a
Company: Warren Cat

State: Unknown
Country: [Not Specified]

Description

Auction Machine add 767 hrs to machine?

Features

- EROPS
- AIR CONDITIONER
- BUCKET

Condition**GENERAL APPEARANCE**

	Condition - Remarks	Parts	Labor
Radiator Grill & Shroud	Good		
Eng. Enclose Hood / Stack	Good		
Fenders	Good		
Fuel Tank	Good		
Crankcase Guard / Battery Box	Good		
Main Frame Welds	Good		
Bumper	Good		
Cab or Canopy	Good - minor bends		
Steps / Ladder	Good		
Grab Irons	Good		
Paint	Fair - scratched up stencils		
Sheet Metal	Good		

	Condition - Remarks	Parts	Labor
S.O.S. Taken	No		
Cleaning Required	No		

SAFETY ITEMS

	Condition - Remarks	Parts	Labor
Safety Decals In Place	Yes		
Safety Decals Legible	Yes		
ROPS	Yes		

	Condition - Remarks	Parts	Labor
Horn	Very Good		
Parking Brake	Very Good		

GAUGES, OPERATOR STATION, CONSOLE

	Condition - Remarks	Parts	Labor
Dash Console	Good		
Meter	Good		
Gauges	Good		
Switches	Good		
Windshield Wipers	Good		
Interior Lights	Good		
Seat Cushion / Arm Rest	Good		
Floor Boards	Good		
EMS Panel / Warnings	Good		
Door Latches	Good		
Glass/Mirrors	Good		
Hydraulic Controls	Fair - one side wet		
Air Conditioner	Good		
Seat Belt	Good		

	Condition - Remarks	Parts	Labor
ROPS Certification Plate	Yes		
Back Up Alarm	Yes		

	Condition - Remarks	Parts	Labor
Fuel Level	1/8		

ENGINE

	Condition - Remarks	Parts	Labor
Oil Leaks	Yes - dirt build up on both sides		
Blow By	No		
Knocking	No		
Water in Oil	No		
Fluid Levels OK?	Yes		

	Condition - Remarks	Parts	Labor

	Condition - Remarks	Parts	Labor
Anti-Freeze Color	red		
Oil Pressure (H/L/N)	normal		
Smoke (B/D/L/W)	balck		

	Condition - Remarks	Parts	Labor
Operating Condition	Good		
Turbocharger / Blower	Good		
Fuel Injection System	Good		
Governor	Good		
Engine Supports	Good		
Air Cleaners	Fair		
Exhaust / Muffler	Good		
Belts / Pulleys	Good - bolts out of belt guard		

————— COOLING SYSTEM —————

	Condition - Remarks	Parts	Labor
Radiator	Fair		
Coolers	Good		
Hoses	Good		
Water Pump	Good		
Fan	Good		
Fan Drive	Good		

	Condition - Remarks	Parts	Labor
Leaks	No - non seen. empty surge tank, rad. low>		

————— ELECTRICAL, STARTING AND CHARGING SYSTEM —————

	Condition - Remarks	Parts	Labor
Batteries / Cables	Good		
Starter	Good		
Alternator	Good		
Wiring	Good		
Pre-Heater	Good		
Lighting	Fair - left rear light broken		

————— TANDEM/GEARS/BEARINGS/CHAINS —————

	Condition - Remarks	Parts	Labor
Front Axle	Good		
Rear Axle	Good		
Travel Motors	Good		
Travel Pumps	Good		
Travel Controls	Good		
Lines / Linkages	Good		
Operating Condition	Good - bob cat controls move both control to travel		

————— HYDRAULICS —————

	Condition - Remarks	Parts	Labor
Operating Condition	Good - Bobcat control left is the lift and right bucket		
Tank	Good		
Pumps & Valves	Fair - joy stick wet		
Hose Lines	Good		
Tilt Cylinder	Good		
Lift Cylinders	Good		

	Condition - Remarks	Parts	Labor
Leaks	No - non seen hyd. oil level low		

————— BUCKET —————

	Condition - Remarks	Parts	Labor
Cutting Edges	Good		
Bucket Bottom	Fair - bent in back		
Bucket Sides	Good		
Bucket Linkage	Good		
Loader Pins & Bushings	Good		
Loader Frame	Good		
Quick Coupler	Fair - stiff handles and not releasing correctly		

————— TIRES —————

	Make / Serial#	Tread Depth in 1/32"	% Life Remaining	Recapped	Tread Cuts/Chunks	Side Cuts Section
Right Front	Caterpillar	9		No	No	No
Left Front		5		No	No	No
Right Rear		11		No	No	No
Left Rear		24		No	No	No
Tire Size	12 - 16.5					

Photos

Click thumbnails to enlarge.





Caterpillar Confidential: Green. Copyright © 2009, Caterpillar Inc. All Rights Reserved.