

	Condition - Remarks	Parts	Labor
S.O.S. Taken	No		
Cleaning Required	No		

SAFETY ITEMS

	Condition - Remarks	Parts	Labor
Safety Decals In Place	Yes		
Safety Decals Legible	No		
ROPS	No		

	Condition - Remarks	Parts	Labor
Horn	Good		
Parking Brake	Good		

GAUGES, OPERATOR STATION, CONSOLE

	Condition - Remarks	Parts	Labor
Dash Console	Good		
Meter	Good		
Gauges	Good		
Switches	Good		
Seat Cushion / Arm Rest	Good		
Floor Boards	Good		
Glass/Mirrors	Good		
Hydraulic Controls	Good		
Seat Belt	Good		

	Condition - Remarks	Parts	Labor
Current Parts Manual	No		
Current Safety Manual	No		
Current O&MM	No		
ROPS Certification Plate	No		
Back Up Alarm	Yes		

ENGINE

	Condition - Remarks	Parts	Labor
Oil Leaks	No		
Blow By	No		
Knocking	No		
Compression in Radiator	No		
Water in Oil	No		
Fluid Levels OK?	Yes		
EPA Decal	No		

	Condition - Remarks	Parts	Labor
Operating			

Condition	Good		
Turbocharger / Blower	Good		
Fuel Injection System	Good		
Governor	Good		
Engine Supports	Good		
Air Cleaners	Good		
Exhaust / Muffler	Good		
Belts / Pulleys	Good		
Oil Filter Condition (CUT)	Good		

————— COOLING SYSTEM —————

	Condition - Remarks	Parts	Labor
Radiator	Good		
Coolers	Good		
Hoses	Good		
Water Pump	Good		
Fan	Good		
Fan Drive	Good		

	Condition - Remarks	Parts	Labor
Leaks	No		

————— ELECTRICAL, STARTING AND CHARGING SYSTEM —————

	Condition - Remarks	Parts	Labor
Batteries / Cables	Good		
Starter	Good		
Alternator	Good		
Wiring	Good		
Pre-Heater	Good		
Lighting	Fair - LR lens cracked, RF light missing		

————— TANDEM/GEARS/BEARINGS/CHAINS —————

	Condition - Remarks	Parts	Labor
Front Axle	Good		
Rear Axle	Good		
Travel Motors	Good		
Travel Pumps	Good		
Travel Controls	Good		
Lines / Linkages	Good		
Operating Condition	Good		

————— HYDRAULICS —————

	Condition - Remarks	Parts	Labor
Operating Condition	Good		
Tank	Good		

Pumps & Valves	Good		
Hose Lines	Good		
Detent Switch	Good		
Tilt Cylinder	Good		
Lift Cylinders	Good		
Filter Condition (CUT)	Good		

	Condition - Remarks	Parts	Labor
Leaks	No		

————— **BUCKET** —————

	Condition - Remarks	Parts	Labor
Cutting Edges	Good		
Teeth / Adapters	Good		
Bucket Bottom	Good		
Bucket Sides	Good		
Bucket Linkage	Good		
Loader Pins & Bushings	Good		
Loader Frame	Good		
Quick Coupler	Good		
Multi Purpose Cylinders	Good		

————— **TIRES** —————

Notes	new tires
--------------	-----------

Caterpillar Confidential: Green. Copyright © 2009, Caterpillar Inc. All Rights Reserved.