

[Delete](#)[«Back to Inspection Results](#)**MUSTANG** **SPECIFICATIONS****2006 CATERPILLAR 252B****Customer Owned Certified****SKID STEER LOADERS**

| | | | |
|---------------------------|-------------------------------|--|------------|
| Inspection Number: | 646108 | Serial #: | SCP02511 |
| Date Created: | 05/06/2009 09:30:37 AM CDT | Engine Serial #: | N/A |
| Last Updated: | 05/06/2009 09:37:39 AM CDT | Transmission Serial #: | N/A |
| Originated By: | John King | SMU/Hrs: | 965 |
| Inspector: | John King | Last Scheduled Oil Sample: | N/A |
| Reviewer: | N/A | Last Cat Track System Inspection: | N/A |
| Salesman: | John King | Last Preventative Maintenance: | N/A |
| Location: | HOUSTON, Texas, United States | Recommendation: | sell as is |
| Asking Price: | N/A | Final Price: | N/A |

Client**Name:** MustangCat**City:** Houston
State: Texas
Country: United States**Features**

- BUCKET
- HYDRAULICS, STANDARD FLOW
- SELF LEVELING

Condition**GENERAL APPEARANCE**

| | Condition - Remarks | Parts | Labor |
|--------------------------------------|---------------------------|-------|-------|
| Radiator Grill & Shroud | Good | | |
| Eng. Enclose Hood / Stack | Good | | |
| Fenders | Good | | |
| Fuel Tank | Good | | |
| Crankcase Guard / Battery Box | Good | | |
| Bumper | Good | | |
| Pre-Cleaner Bowl | Good | | |
| Cab or Canopy | Fair - slight dent on top | | |
| Steps / Ladder | Good | | |
| Grab Irons | Good | | |
| Paint | Good | | |
| Sheet Metal | Good | | |

| | Condition - Remarks | Parts | Labor |
|--------------------------|---------------------|-------|-------|
| S.O.S. Taken | No | | |
| Cleaning Required | No | | |

SAFETY ITEMS

| | Condition - Remarks | Parts | Labor |
|------------------------|---------------------|-------|-------|
| Safety Decals In Place | Yes | | |
| Safety Decals Legible | Yes | | |
| ROPS | No | | |

| | Condition - Remarks | Parts | Labor |
|---------------|---------------------|-------|-------|
| Horn | Poor - didnt work | | |
| Parking Brake | Good | | |

GAUGES, OPERATOR STATION, CONSOLE

| | Condition - Remarks | Parts | Labor |
|-------------------------|---------------------|-------|-------|
| Dash Console | Good | | |
| Meter | Good | | |
| Gauges | Good | | |
| Switches | Good | | |
| Interior Lights | Good | | |
| Seat Cushion / Arm Rest | Good | | |
| Floor Boards | Good | | |
| EMS Panel / Warnings | Good | | |
| Glass/Mirrors | Good | | |
| Hydraulic Controls | Good | | |
| Seat Belt | Good | | |

| | Condition - Remarks | Parts | Labor |
|--------------------------|---------------------|-------|-------|
| Current Parts Manual | No | | |
| Current Safety Manual | No | | |
| Current O&MM | No | | |
| ROPS Certification Plate | No | | |
| Back Up Alarm | Yes | | |

ENGINE

| | Condition - Remarks | Parts | Labor |
|-------------------------|---------------------|-------|-------|
| Oil Leaks | No | | |
| Blow By | No | | |
| Knocking | No | | |
| Compression in Radiator | No | | |
| Water in Oil | No | | |
| Fluid Levels OK? | Yes | | |

| | Condition - Remarks | Parts | Labor |
|---------------------|---------------------|-------|-------|
| Operating Condition | Good | | |
| Turbocharger / | Good | | |

| | | | |
|------------------------------|------|--|--|
| Blower | | | |
| Fuel Injection System | Good | | |
| Governor | Good | | |
| Engine Supports | Good | | |
| Air Cleaners | Good | | |
| Exhaust / Muffler | Good | | |
| Belts / Pulleys | Good | | |

————— COOLING SYSTEM —————

| | Condition - Remarks | Parts | Labor |
|-------------------|----------------------------|--------------|--------------|
| Radiator | Good | | |
| Coolers | Good | | |
| Hoses | Good | | |
| Water Pump | Good | | |
| Fan | Good | | |
| Fan Drive | Good | | |

| | Condition - Remarks | Parts | Labor |
|--------------|----------------------------|--------------|--------------|
| Leaks | No | | |

————— ELECTRICAL, STARTING AND CHARGING SYSTEM —————

| | Condition - Remarks | Parts | Labor |
|---------------------------|----------------------------|--------------|--------------|
| Batteries / Cables | Good | | |
| Starter | Good | | |
| Alternator | Good | | |
| Wiring | Good | | |
| Pre-Heater | Good | | |
| Lighting | Good | | |

————— TANDEM/GEARS/BEARINGS/CHAINS —————

| | Condition - Remarks | Parts | Labor |
|----------------------------|----------------------------|--------------|--------------|
| Front Axle | Good | | |
| Rear Axle | Good | | |
| Travel Motors | Good | | |
| Travel Controls | Good | | |
| Lines / Linkages | Good | | |
| Operating Condition | Good | | |

————— HYDRAULICS —————

| | Condition - Remarks | Parts | Labor |
|----------------------------|----------------------------|--------------|--------------|
| Operating Condition | Good | | |
| Tank | Good | | |
| Pumps & Valves | Good | | |
| Hose Lines | Good | | |
| Detent Switch | Good | | |
| Tilt Cylinder | Good | | |

| | | | |
|------------------------|------|--|--|
| Lift Cylinders | Good | | |
| Filter Condition (CUT) | Good | | |

| | | | |
|-------|----------------------------|--------------|--------------|
| | Condition - Remarks | Parts | Labor |
| Leaks | No | | |

————— BUCKET —————

| | | | |
|-------------------------|----------------------------|--------------|--------------|
| | Condition - Remarks | Parts | Labor |
| Cutting Edges | Very Good | | |
| Teeth / Adapters | Very Good | | |
| Bucket Bottom | Very Good | | |
| Bucket Sides | Very Good | | |
| Bucket Linkage | Good | | |
| Loader Pins & Bushings | Good | | |
| Loader Frame | Good | | |
| Quick Coupler | Good | | |
| Multi Purpose Cylinders | Good | | |

| | | | |
|-----------------|----------------------------|--------------|--------------|
| | Condition - Remarks | Parts | Labor |
| Bucket Capacity | 72" GP bucket | | |

————— TIRES —————

| | Make / Serial# | Tread Depth in 1/32" | % Life Remaining | Recapped | Tread Cuts/Chunks | Side Cuts Section |
|-------------|----------------|----------------------|------------------|----------|-------------------|-------------------|
| Right Front | | | 100 | | | |
| Left Front | | | 100 | | | |
| Right Rear | | | 100 | | | |
| Left Rear | | | 100 | | | |
| Notes | new tires | | | | | |

Caterpillar Confidential: Green. Copyright © 2009, Caterpillar Inc. All Rights Reserved.