

**Louisiana
Machinery**

SPECIFICATIONS
2005 CATERPILLAR 257B
Customer Owned Certified
MULTI TERRAIN LOADERS

| | | | |
|---------------------------|-------------------------------|--|-------------------|
| Inspection Number: | 647428 | Serial #: | SLK03479 |
| Date Created: | 05/18/2009 10:29:22 AM CDT | Engine Serial #: | N/A |
| Last Updated: | 05/19/2009 12:16:44 PM CDT | Transmission Serial #: | N/A |
| Originated By: | Samy Cashio | SMU/Hrs: | 971 |
| Inspector: | N/A | Last Scheduled Oil Sample: | N/A |
| Reviewer: | N/A | Last Cat Track System Inspection: | N/A |
| Salesman: | N/A | Last Preventative Maintenance: | N/A |
| Location: | HOUSTON, Texas, United States | Recommendation: | no recommendation |
| Asking Price: | N/A | Final Price: | N/A |

Client
Name: Louisiana Machinery

City: RESERVE

State: Louisiana

Country: United States

Description

1.) Machine was last serviced on 5/11/09 at 970 Hours.(1000 HR. PM.)

Features

- EROPS
- AIR CONDITIONER
- HEATER
- BUCKET
- AUXILIARY HYDRAULICS
- SELF LEVELING

Condition
GENERAL APPEARANCE

| | Condition - Remarks | Parts | Labor |
|--------------------------------------|--|-------|-------|
| Radiator Grill & Shroud | Good | | |
| Eng. Enclose Hood / Stack | Good | | |
| Fenders | Good | | |
| Fuel Tank | Good | | |
| Crankcase Guard / Battery Box | Good | | |
| Main Frame Welds | Very Good | | |
| Cab or Canopy | Good | | |
| Steps / Ladder | Good - Step at bucket is slightly bent (but is ok) | | |
| Grab Irons | Good - No Grab iron for left side of machine | | |
| Paint | Good | | |
| Sheet Metal | Good | | |

| | Condition - Remarks | Parts | Labor |
|-------------------|---------------------|-------|-------|
| S.O.S. Taken | No | | |
| Cleaning Required | No | | |

SAFETY ITEMS

| | Condition - Remarks | Parts | Labor |
|------------------------|---------------------|-------|-------|
| Safety Decals In Place | Yes | | |
| Safety Decals Legible | Yes | | |
| ROPS | Yes - ROPS | | |

| | Condition - Remarks | Parts | Labor |
|---------------|---------------------|-------|-------|
| Horn | Good | | |
| Parking Brake | Good | | |

GAUGES, OPERATOR STATION, CONSOLE

| | Condition - Remarks | Parts | Labor |
|-------------------------|---------------------|-------|-------|
| Dash Console | Good | | |
| Meter | Good | | |
| Gauges | Good | | |
| Switches | Good | | |
| Windshield Wipers | Good | | |
| Heater | Good | | |
| Interior Lights | Good | | |
| Seat Cushion / Arm Rest | Good | | |
| Floor Boards | Good | | |
| EMS Panel / Warnings | Good | | |
| Door Latches | Good | | |
| Glass/Mirrors | Good | | |
| Hydraulic Controls | Good | | |
| Air Conditioner | Good - Blows Cold | | |

| | Condition - Remarks | Parts | Labor |
|--------------------------|---------------------|-------|-------|
| Current Safety Manual | Yes | | |
| ROPS Certification Plate | Yes | | |
| Back Up Alarm | Yes | | |

ENGINE

| | Condition - Remarks | Parts | Labor |
|-------------------------|-------------------------|-------|-------|
| Oil Leaks | No | | |
| Blow By | No | | |
| Knocking | No | | |
| Compression in Radiator | No - Normal Circulation | | |
| Water in Oil | No | | |
| Fluid Levels OK? | Yes | | |

| | Condition - Remarks | Parts | Labor |
|--|---------------------|-------|-------|
| | | | |

| | | | |
|-----------------------------------|--------------------|--|--|
| Operating Condition | Good | | |
| Turbocharger / Blower | Good | | |
| Fuel Injection System | Good | | |
| Governor | Good | | |
| Engine Supports | Good | | |
| Air Cleaners | Good | | |
| Exhaust / Muffler | Good | | |
| Belts / Pulleys | Good | | |
| Oil Filter Condition (CUT) | Good - DID NOT CUT | | |

————— COOLING SYSTEM —————

| | Condition - Remarks | Parts | Labor |
|-------------------|----------------------------|--------------|--------------|
| Radiator | Good | | |
| Coolers | Good | | |
| Hoses | Good | | |
| Water Pump | Good | | |
| Fan | Good | | |
| Fan Drive | Good | | |

| | Condition - Remarks | Parts | Labor |
|--------------|----------------------------|--------------|--------------|
| Leaks | No | | |

————— ELECTRICAL, STARTING AND CHARGING SYSTEM —————

| | Condition - Remarks | Parts | Labor |
|---------------------------|------------------------------------|--------------|--------------|
| Batteries / Cables | Very Good | | |
| Starter | Very Good | | |
| Alternator | Very Good | | |
| Wiring | Very Good | | |
| Lighting | Very Good - All lights are working | | |

————— TANDEM/GEARS/BEARINGS/CHAINS —————

| | Condition - Remarks | Parts | Labor |
|----------------------------|----------------------------|--------------|--------------|
| Front Axle | Good | | |
| Rear Axle | Good | | |
| Travel Motors | Good | | |
| Travel Pumps | Good | | |
| Travel Controls | Good | | |
| Lines / Linkages | Good | | |
| Operating Condition | Good | | |

————— HYDRAULICS —————

| | Condition - Remarks | Parts | Labor |
|----------------------------|----------------------------|--------------|--------------|
| Operating Condition | Good | | |
| Tank | Good | | |
| Pump & Valves | Good | | |
| Hoses / Lines | Good | | |

| | | | |
|-------------------------------|--------------------|--|--|
| Detent Switch | Good | | |
| Tilt Cylinder | Good | | |
| Lift Cylinders | Good | | |
| Filter Condition (CUT) | Good - DID NOT CUT | | |

| | Condition - Remarks | Parts | Labor |
|--------------|----------------------------|--------------|--------------|
| Leaks | No | | |

———— ATTACHMENTS / WORK TOOLS ————

| | Condition - Remarks | Parts | Labor |
|----------------------------|----------------------------|--------------|--------------|
| Operating Condition | Good | | |

———— BUCKET ————

| | Condition - Remarks | Parts | Labor |
|-----------------------------------|--|--------------|--------------|
| Cutting Edges | Good | | |
| Bucket Bottom | Good | | |
| Bucket Sides | Good | | |
| Bucket Linkage | Good | | |
| Loader Pins & Bushings | Good | | |
| Loader Frame | Good | | |
| Quick Coupler | Good - Manual | | |
| Notes | 66" General Purpose Bucket with Bolt on Edge | | |

———— UNDERCARRIAGE ————

| | Condition - Remarks | Parts | Labor |
|-------------------------------|---|--------------|--------------|
| Roller | Good | | |
| Track / Belt Condition | Good | | |
| Roller Frame | Good | | |
| Idlers | Good | | |
| Sprocket | Good | | |
| Notes | 15" Rubber Tracks, Good thickness left on Undercarriage for all components. | | |