

[« Back to Equipment Editing](#)



SPECIFICATIONS

2005 CATERPILLAR 287B (Used)
MULTI TERRAIN LOADERS

NOVI, Michigan, United States

Catalog #: CU945764 Serial #: ZSA01475 SMU/Hrs: 2364 Rating: GOOD

[Detailed View](#) [More Photos](#) [Additional Information](#)



MICHIGAN CAT
 12550 23 Mile Road
 Shelby Township, Michigan 48315
 United States

[More Photos »](#)

Features

- EROPS
- HEATER
- COUPLER, HYDRAULIC
- AUXILIARY HYDRAULICS
- AIR CONDITIONER
- BUCKET
- FORKS
- HYDRAULICS, STANDARD FLOW

Condition

GENERAL APPEARANCE

Radiator Grill & Shroud	Good
Eng. Enclose Hood / Stack	Good
Fenders	Good
Fuel Tank	Good
Crankcase Guard / Battery Box	Good
Main Frame Welds	Good
Bumper	Good

Counterweight	Good
Pre-Cleaner Bowl	Good
Cab or Canopy	Good
Steps / Ladder	Good
Grab Irons	Good
Paint	Fair
Sheet Metal	Good

SAFETY ITEMS

ROPS	Yes
------	-----

Horn	Good
------	------

Parking Brake	Good
---------------	------

GAUGES, OPERATOR STATION, CONSOLE

Dash Console	Good
Meter	Good
Gauges	Good
Switches	Good
Heater	Good

Seat Cushion / Arm Rest	Good
EMS Panel / Warnings	Good
Door Latches	Good
Glass/Mirrors	Good
Air Conditioner	Good

Current Parts Manual	No
Current Safety Manual	No

Current O&MM	No
--------------	----

ENGINE

Oil Leaks	No
Blow By	No
Knocking	No

Water in Oil	No
Fluid Levels OK?	Yes

Oil Pressure (H/L/N)	NORMAL
----------------------	--------

Smoke (B/D/L/W)	NORMAL
-----------------	--------

Air Cleaners	Good
Exhaust / Muffler	Good

Belts / Pulleys	Good
-----------------	------

COOLING SYSTEM

Radiator	Good
----------	------

Hoses	Good
-------	------

Leaks	No
-------	----

ELECTRICAL, STARTING AND CHARGING SYSTEM

Batteries / Cables	Good
Starter	Good
Alternator	Good

Wiring	Good
Lighting	Good

Block Heater	No
--------------	----

Ether Aid	No
-----------	----

TANDEMS/GEARS/BEARINGS/CHAINS

Front Axle	Good
Rear Axle	Good
Travel Motors	Good
Travel Pumps	Good

Travel Controls	Good
Lines / Linkages	Good
Operating Condition	Good

HYDRAULICS

Operating Condition	Good
Tank	Good
Pump & Valves	Good
Hoses / Lines	Good

Detent Switch	Good
Tilt Cylinder	Good
Lift Cylinders	Good
Filter Condition (CUT)	Good

Leaks	No
--------------	----

BUCKET

Cutting Edges	Good
Bucket Bottom	Good
Bucket Sides	Good
Bucket Linkage	Good

Loader Pins & Bushings	Good
Loader Frame	Good
Quick Coupler	Good

Bucket Capacity	78"
------------------------	-----

UNDERCARRIAGE

Roller	Good - SOME CHIPS
Track / Belt Condition	Good
Roller Frame	Good

Idlers	Good
Sprocket	Very Good - ROLLERS REPLACED @1600 HOURS

% Worn	LEFT 70%, RIGHT 50%
---------------	---------------------

Prices subject to change without notice.

Caterpillar Confidential: Green. Copyright © 2009, Caterpillar Inc. All Rights Reserved.