

[«Back to Inspection Results](#)**ZIEGLER** **CAT****SPECIFICATIONS****2002 CATERPILLAR 277****Customer Owned Certified****MULTI TERRAIN LOADERS**

Inspection Number:	614230	Serial #:	CNC00544
Date Created:	03/20/2009 03:56:46 PM CDT	Engine Serial #:	3NW22852
Last Updated:	03/20/2009 04:09:08 PM CDT	Transmission Serial #:	N/A
Originated By:	Adam Kosel	SMU/Hrs:	3318
Inspector:	Adam Kosel	Last Scheduled Oil Sample:	N/A
Reviewer:	N/A	Last Cat Track System Inspection:	N/A
Salesman:	N/A	Last Preventative Maintenance:	N/A
Location:	ELKO, Minnesota, United States	Recommendation:	no recommendation
Asking Price:	N/A		

Client

Name: State: Unknown
Company: Cat Auction Services **Country:** [Not Specified]

Features

- OROPS
- BUCKET
- AUXILIARY HYDRAULICS
- SELF LEVELING

Condition**GENERAL APPEARANCE**

	Condition - Remarks	Parts	Labor
Radiator Grill & Shroud	Good		
Eng. Enclose Hood / Stack	Good		
Fuel Tank	Good		
Crankcase Guard / Battery Box	Good		
Main Frame Welds	Good		
Bumper	Good		
Counterweight	Good		
Cab or Canopy	Good		
Steps / Ladder	Good		
Grab Irons	Good		
Paint	Good		
Sheet Metal	Good		

	Condition - Remarks	Parts	Labor
S.O.S. Taken	No		
Cleaning Required	No		

SAFETY ITEMS

	Condition - Remarks	Parts	Labor
Safety Decals In Place	Yes		
Safety Decals Legible	Yes		
ROPS	Yes		

	Condition - Remarks	Parts	Labor
Horn	Good		
Parking Brake	Good		

GAUGES, OPERATOR STATION, CONSOLE

	Condition - Remarks	Parts	Labor
Dash Console	Good		
Meter	Good		
Gauges	Good		
Switches	Good		
Heater	Good		
Seat Cushion / Arm Rest	Good		
Floor Boards	Good		
EMS Panel / Warnings	Good		
Glass/Mirrors	Good		
Hydraulic Controls	Good		

	Condition - Remarks	Parts	Labor
Current Parts Manual	Yes		
Current Safety Manual	Yes		
Current O&MM	Yes		
ROPS Certification Plate	Yes		
Back Up Alarm	Yes		

ENGINE

	Condition - Remarks	Parts	Labor
Oil Leaks	No		
Blow By	No		
Knocking	No		
Compression in Radiator	No		
Water in Oil	No		
Fluid Levels OK?	Yes		
EPA Decal	No		

	Condition - Remarks	Parts	Labor
Anti-Freeze Color	Orange		
Oil Pressure (H/L/N)	Normal		

Smoke (B/D/L/W)	Normal		
-----------------	--------	--	--

	Condition - Remarks	Parts	Labor
Operating Condition	Good		
Turbocharger / Blower	Good		
Fuel Injection System	Good		
Governor	Good		
Engine Supports	Good		
Air Cleaners	Good		
Exhaust / Muffler	Good		
Belts / Pulleys	Good		

————— COOLING SYSTEM —————

	Condition - Remarks	Parts	Labor
Radiator	Good		
Coolers	Good		
Hoses	Good		
Water Pump	Good		
Fan	Good		
Fan Drive	Good		

	Condition - Remarks	Parts	Labor
Leaks	No		

————— ELECTRICAL, STARTING AND CHARGING SYSTEM —————

	Condition - Remarks	Parts	Labor
Batteries / Cables	Good		
Starter	Good		
Alternator	Good		
Wiring	Good		
Pre-Heater	Good		
Lighting	Good		

	Condition - Remarks	Parts	Labor
Block Heater	Yes		
Ether Aid	No		

————— TANDEM/GEARS/BEARINGS/CHAINS —————

	Condition - Remarks	Parts	Labor
Travel Motors	Good		
Travel Pumps	Good		
Travel Controls	Good		
Lines / Linkages	Good		
Operating Condition	Good		

————— HYDRAULICS —————

	Condition - Remarks	Parts	Labor
Operating Condition	Good		
Tank	Good		
Pump & Valves	Good		
Hoses / Lines	Good		
Detent Switch	Good		
Tilt Cylinder	Good		
Lift Cylinders	Good		

	Condition - Remarks	Parts	Labor
Leaks	No		

ATTACHMENTS / WORK TOOLS

	Condition - Remarks	Parts	Labor
Operating Condition	Good		

BUCKET

	Condition - Remarks	Parts	Labor
Cutting Edges	New - New		
Bucket Bottom	Good		
Bucket Sides	Good		
Bucket Linkage	Good		
Loader Pins & Bushings	Good		
Loader Frame	Good		
Quick Coupler	Good - Manual		

	Condition - Remarks	Parts	Labor
Bucket Capacity	79" Cat GP Bkt		

UNDERCARRIAGE


	Condition - Remarks	Parts	Labor
Roller	Fair - Showing wear		
Track / Belt Condition	Fair - Left 25% Right 75%		
Roller Frame	Good		
Idlers	Fair		
Sprocket	Good		
Notes	ASV undercarriage		


COMMENTS, MISC. REPAIRS, GENERAL REMARKS

	Parts	Labor
Machine runs good and appears to be in good operating condition.		

Photos

Click thumbnails to enlarge.





Caterpillar Confidential: Green. Copyright © 2009, Caterpillar Inc. All Rights Reserved.