

[«Back to Inspection Results](#)**ZIEGLER** **CAT****SPECIFICATIONS****BOBCAT / INGERSOLL-RAND T300****Customer Owned Certified****SKID STEER LOADERS**

Inspection Number:	612393	Serial #:	532011709
Date Created:	03/18/2009 01:24:42 PM CDT	Engine Serial #:	5S3271
Last Updated:	03/18/2009 01:33:49 PM CDT	Transmission Serial #:	N/A
Originated By:	Adam Kosel	SMU/Hrs:	1559
Inspector:	Adam Kosel	Last Scheduled Oil Sample:	N/A
Reviewer:	N/A	Last Cat Track System Inspection:	N/A
Salesman:	N/A	Last Preventative Maintenance:	N/A
Location:	ELKO, Minnesota, United States	Recommendation:	no recommendation
Asking Price:	N/A		

Client

Name: State: Unknown
Company: Cat Auction Services **Country:** [Not Specified]

Features

- EROPS
- HEATER
- BUCKET
- COUPLER, HYDRAULIC
- AUXILIARY HYDRAULICS
- HYDRAULICS, STANDARD FLOW

Condition**GENERAL APPEARANCE**

	Condition - Remarks	Parts	Labor
Radiator Grill & Shroud	Good		
Eng. Enclose Hood / Stack	Good		
Fuel Tank	Good		
Crankcase Guard / Battery Box	Good		
Main Frame Welds	Good		
Bumper	Good		
Counterweight	Good		
Cab or Canopy	Good		
Steps / Ladder	Good		
Grab Irons	Good		
Paint	Good		
Sheet Metal	Good		

	Condition - Remarks	Parts	Labor
S.O.S. Taken	No		
Cleaning Required	No		

SAFETY ITEMS

	Condition - Remarks	Parts	Labor
Safety Decals In Place	Yes		
Safety Decals Legible	Yes		
ROPS	Yes		

	Condition - Remarks	Parts	Labor
Horn	Good		
Parking Brake	Good		

GAUGES, OPERATOR STATION, CONSOLE

	Condition - Remarks	Parts	Labor
Dash Console	Good		
Meter	Good		
Gauges	Good		
Switches	Good		
Windshield Wipers	Good		
Heater	Good		
Seat Cushion / Arm Rest	Good		
Floor Boards	Good		
EMS Panel / Warnings	Good		
Door Latches	Good		
Glass/Mirrors	Good		
Hydraulic Controls	Good		
Seat Belt	Good		

	Condition - Remarks	Parts	Labor
Current Parts Manual	No		
Current Safety Manual	No		
Current O&MM	No		
ROPS Certification Plate	Yes		
Back Up Alarm	Yes		

ENGINE

	Condition - Remarks	Parts	Labor
Oil Leaks	No		
Blow By	No		
Knocking	No		
Compression in Radiator	No		
Water in Oil	No		
Fluid Levels OK?	Yes		
EPA Decal	No		

	Condition - Remarks	Parts	Labor
--	---------------------	-------	-------

Anti-Freeze Color	Green		
Oil Pressure (H/L/N)	Normal		
Smoke (B/D/L/W)	Normal		

	Condition - Remarks	Parts	Labor
Operating Condition	Good		
Turbocharger / Blower	Good		
Fuel Injection System	Good		
Governor	Good		
Engine Supports	Good		
Air Cleaners	Good		
Exhaust / Muffler	Good		
Belts / Pulleys	Good		

————— COOLING SYSTEM —————

	Condition - Remarks	Parts	Labor
Radiator	Good		
Coolers	Good		
Hoses	Good		
Water Pump	Good		
Fan	Good		
Fan Drive	Good		

	Condition - Remarks	Parts	Labor
Leaks	No		

————— ELECTRICAL, STARTING AND CHARGING SYSTEM —————

	Condition - Remarks	Parts	Labor
Batteries / Cables	Good		
Starter	Good		
Alternator	Good		
Wiring	Good		
Pre-Heater	Good		
Lighting	Good		

	Condition - Remarks	Parts	Labor
Block Heater	Yes		
Ether Aid	No		

————— TANDEM/S/GEARS/BEARINGS/CHAINS —————

	Condition - Remarks	Parts	Labor
Travel Motors	Good		
Travel Pumps	Good		
Travel Controls	Good		
Lines / Linkages	Good		
Operating Condition	Good		

HYDRAULICS

	Condition - Remarks	Parts	Labor
Operating Condition	Good		
Tank	Good		
Pumps & Valves	Good		
Hose Lines	Good		
Detent Switch	Good		
Tilt Cylinder	Good		
Lift Cylinders	Good		
Notes	3 line aux hyd		

	Condition - Remarks	Parts	Labor
Leaks	No		

ATTACHMENTS / WORK TOOLS

	Condition - Remarks	Parts	Labor
Operating Condition	Good		

BUCKET

	Condition - Remarks	Parts	Labor
Cutting Edges	Poor - Cutting edge is completely worn out		
Bucket Bottom	Good		
Bucket Sides	Good		
Bucket Linkage	Good		
Loader Pins & Bushings	Fair - Loose		
Loader Frame	Good		
Quick Coupler	Good		
Multi Purpose Cylinders	Good		

	Condition - Remarks	Parts	Labor
Bucket Capacity	73" GP bucket		

TIRES

Tire Size	Machine has tracks, tracks are 50% and the u/c is in good condition.		
-----------	--	--	--

	Condition - Remarks	Parts	Labor
Spare	No		
Floatation Chains / Tracks	Yes		

	Condition - Remarks	Parts	Labor
% Remaining on Chains / Tracks	50%		

COMMENTS, MISC. REPAIRS, GENERAL REMARKS

	Parts	Labor

Machine runs good and is in good operating condition.

Photos

Click thumbnails to enlarge.



Caterpillar Confidential: Green. Copyright © 2009, Caterpillar Inc. All Rights Reserved.